



Product Change Notification

110750 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110750 - 00
Change Title: Intel® Solid-State Drive, PCN 110750-00,
Product Marking, Label, KCC Logo Change
Date of Publication: June 07, 2011

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Jun 27, 2011 |
|---|--------------|

Description of Change to the Customer:

Korean Government has introduced a new KCC Logo. Intel SSDs will transition from the old logo to new logo on the entire product label. Please see pictures and details below.

| Old Logo to New Logo (Picture) | |
|--|---------------------|
| | |
| Dimension of New Logo | |
| | |
| Registration Number Changes (under the logo) | |
| 2.5" SSD | KCC-REM-CPU-SSDSA2X |
| 1.8" SSD | KCC-REM-CPU-SSDSA1X |
| mSATA SSD | KCC-REM-CPU-mSATA |

Customer Impact of Change and Recommended Action:

Intel does not anticipate any customer impact.

Products Affected / Intel Ordering Codes:

| Pre Change MM# | Pre Change Product Code | Pre Change TA | Post Change TA | Post Change SA | Post Change SA |
|----------------|-------------------------|---------------|----------------|----------------|----------------|
| 896432 | SSDSA2SH032G101896432 | E41511-907 | E41511-908 | E41512-907 | E41512-908 |
| 896474 | SSDSA2SH032G1 896474 | E41514-907 | E41514-908 | E41512-907 | E41512-908 |
| 899386 | SSDSA2SH064G101899386 | E62121-906 | E62121-907 | E56514-905 | E56514-906 |
| 899387 | SSDSA2SH064G1 899387 | E58005-906 | E58005-907 | E56514-905 | E56514-906 |
| 900342 | SSDSA2SH032G1C5900342 | E52339-907 | E52339-908 | E41512-907 | E41512-908 |
| 901316 | SSDSA2SH064G1C5901316 | E56510-905 | E56510-906 | E56514-905 | E56514-906 |
| 901933 | SSDSA2MH160G2 901933 | E64371-311 | E64371-312 | E70560-311 | E70560-312 |
| 901934 | SSDSA2MH080G2 901934 | E64370-311 | E64370-312 | E70559-311 | E70559-312 |
| 901936 | SSDSA1MH160G2 901936 | E64369-311 | E64369-312 | E70557-311 | E70557-312 |
| 901937 | SSDSA1MH080G2 901937 | E65912-311 | E65912-312 | E70556-311 | E70556-312 |
| 902211 | SSDSA2MH080G2C 902211 | E92443-311 | E92443-312 | E64510-311 | E64510-312 |
| 902383 | SSDSA2MH080G2C1902383 | E64508-311 | E64508-312 | E64510-311 | E64510-312 |
| 902384 | SSDSA2MH160G2C1902384 | E64509-311 | E64509-312 | E64511-311 | E64511-312 |
| 902462 | SSDSA2MH080G2R5902462 | E65910-312 | E65910-313 | E87240-204 | E87240-205 |
| 902464 | SSDSA2MH160G2R5902464 | E65907-311 | E65907-312 | E64511-311 | E64511-312 |
| 903844 | SSDSA1MH160G201903844 | E74780-311 | E74780-312 | E70557-311 | E70557-312 |
| 903845 | SSDSA1MH080G201903845 | E74781-311 | E74781-312 | E70556-311 | E70556-312 |
| 903846 | SSDSA2MH160G201903846 | E74784-311 | E74784-312 | E70560-311 | E70560-312 |
| 903847 | SSDSA2MH080G201903847 | E74785-311 | E74785-312 | E70559-311 | E70559-312 |
| 904580 | SSDSA2MP040G2C1904580 | E78153-312 | E78153-313 | E78155-312 | E78155-313 |
| 905205 | SSDSA2MP040G2R5905205 | E83497-313 | E83497-314 | E87243-204 | E87243-205 |
| 906056 | SSDSA2MJ080G2C1906056 | E87238-204 | E87238-205 | E87240-204 | E87240-205 |
| 906102 | SSDSA2MJ080G201906102 | E87253-204 | E87253-205 | E75392-204 | E75392-205 |
| 906574 | SSDSA2MQ040G2C1906574 | E87256-204 | E87256-205 | E87243-204 | E87243-205 |
| 908110 | SSDSA2MJ080G2 908110 | E92951-204 | E92951-205 | E75392-204 | E75392-205 |
| 908699 | SSDMAEMC040G2C1908699 | G11897-503 | G11897-504 | G11900-503 | G11900-504 |
| 908700 | SSDMAEMC040G2 908700 | G11898-503 | G11898-504 | G11900-503 | G11900-504 |
| 908703 | SSDMAEMC080G2C1908703 | G11968-503 | G11968-504 | G11970-503 | G11970-504 |
| 908704 | SSDMAEMC080G2 908704 | G11969-503 | G11969-504 | G11970-503 | G11970-504 |

| Pre Change MM# | Pre Change Product Code | Pre Change TA | Post Change TA | Post Change SA | Post Change SA |
|-----------------------|--------------------------------|----------------------|-----------------------|-----------------------|-----------------------|
| 909118 | SSDSA2MH080G2K5909118 | G11143-101 | G11143-102 | E87240-204 | E87240-205 |
| 909119 | SSDSA2MH160G2K5909119 | G11144-101 | G11144-102 | E64511-311 | E64511-312 |
| 909120 | SSDSA2MP040G2K5909120 | G11139-101 | G11139-102 | E87243-204 | E87243-205 |
| 909428 | SSDSA2CW160G3K5909428 | G17906-602 | G17906-603 | G17907-601 | G17907-602 |
| 909429 | SSDSA2CW300G3K5909429 | G12088-602 | G12088-603 | G12224-601 | G12224-602 |
| 909441 | SSDSA2CW600G3K5909441 | G17908-602 | G17908-603 | G17909-601 | G17909-602 |
| 909442 | SSDSA2CW080G3K5909442 | G17904-602 | G17904-603 | G17905-601 | G17905-602 |
| 909443 | SSDSA2CT040G3K5909443 | G17902-602 | G17902-603 | G17903-601 | G17903-602 |
| 910281 | SSDSA2MH120G2K5910281 | G15693-104 | G15693-105 | G15695-104 | G15695-105 |
| 910838 | SSDSA2CT040G301910838 | G23974-601 | G23974-602 | G17903-601 | G17903-602 |
| 910840 | SSDSA2CW080G301910840 | G23975-601 | G23975-602 | G17905-601 | G17905-602 |
| 910841 | SSDSA2CW160G301910841 | G23976-601 | G23976-602 | G17907-601 | G17907-602 |
| 910842 | SSDSA2CW300G301910842 | G23977-601 | G23977-602 | G12224-601 | G12224-602 |
| 910843 | SSDSA2CW600G301910843 | G23978-601 | G23978-602 | G17909-601 | G17909-602 |
| 911129 | SSDSA2CT040G3B5911129 | G23979-601 | G23979-602 | G17903-601 | G17903-602 |
| 911130 | SSDSA2CW080G3B5911130 | G23980-601 | G23980-602 | G17905-601 | G17905-602 |
| 911131 | SSDSA2CW160G3B5911131 | G23982-601 | G23982-602 | G17907-601 | G17907-602 |
| 911132 | SSDSA2CW300G3B5911132 | G23983-601 | G23983-602 | G12224-601 | G12224-602 |
| 911133 | SSDSA2CW600G3B5911133 | G23984-601 | G23984-602 | G17909-601 | G17909-602 |
| 911564 | SSDSA2CW120G3B5911564 | G23981-601 | G23981-602 | G22723-601 | G22723-602 |
| 911565 | SSDSA2CW120G3K5911565 | G22722-602 | G22722-603 | G22723-601 | G22723-602 |
| 911566 | SSDSA2CW120G301911566 | G23973-601 | G23973-602 | G22723-601 | G22723-602 |
| 911567 | SSDSA2BW120G301911567 | G34235-601 | G34235-602 | G34237-601 | G34237-602 |
| 913155 | SSDSA2MP040G2C 913155 | G22601-204 | G22601-205 | E87243-204 | E87243-205 |
| 913156 | SSDSA2MH120G2C 913156 | G22602-104 | G22602-105 | G15695-104 | G15695-105 |
| 913229 | SSDSA2BW160G301913229 | G34233-601 | G34233-602 | G33021-601 | G33021-602 |
| 913230 | SSDSA2BW080G301913230 | G34232-601 | G34232-602 | G33019-601 | G33019-602 |
| 913231 | SSDSA2CT040G310913231 | G24396-601 | G24396-602 | G17903-601 | G17903-602 |
| 913232 | SSDSA2CW080G310913232 | G24397-601 | G24397-602 | G17905-601 | G17905-602 |
| 913233 | SSDSA2CW120G310913233 | G24398-601 | G24398-602 | G22723-601 | G22723-602 |
| 913234 | SSDSA2CW160G310913234 | G24399-601 | G24399-602 | G17907-601 | G17907-602 |

| Pre Change MM# | Pre Change Product Code | Pre Change TA | Post Change TA | Post Change SA | Post Change SA |
|-----------------------|--------------------------------|----------------------|-----------------------|-----------------------|-----------------------|
| 913235 | SSDSA2CW300G310913235 | G24400-601 | G24400-602 | G12224-601 | G12224-602 |
| 913236 | SSDSA2CW600G310913236 | G24401-601 | G24401-602 | G17909-601 | G17909-602 |
| 916317 | SSDSA2BW600G301916317 | G33016-601 | G33016-602 | G33017-601 | G33017-602 |
| 916318 | SSDSA2BT040G301916318 | G33009-601 | G33009-602 | G33010-601 | G33010-602 |
| 916319 | SSDSA2BW300G301916319 | G33012-601 | G33012-602 | G33013-601 | G33013-602 |
| 916321 | SSDSA2BT040G3 916321 | G33011-601 | G33011-602 | G33010-601 | G33010-602 |
| 916322 | SSDSA2BW080G3 916322 | G33018-601 | G33018-602 | G33019-601 | G33019-602 |
| 916323 | SSDSA2BW160G3 916323 | G33020-601 | G33020-602 | G33021-601 | G33021-602 |
| 916324 | SSDSA2BW300G3 916324 | G33014-601 | G33014-602 | G33013-601 | G33013-602 |

PCN Revision History:

Date of Revision:

June 7, 2011

Revision Number:

00

Reason:

Originally Published PCN