



Product Change Notification

107755 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107755 - 00

**Change Title: D946GZIS, PCN 107755-00,
Product Material, Adding new FET
and update to latest BIOS**

Date of Publication: July 24, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 23, 2007
---	--------------

Description of Change to the Customer:

A new FET for 5V dual circuit will be added to ensure healthy material supply line and the latest BIOS will be updated to Intel Desktop Board D946GZIS

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Pre Change PBA	Post Change AA	Post Change PBA
LAD946GZISL 880261	880261	D45436-501	D45437-501	D45436-502	D45437-502
BLKD946GZISSL 882970	882970	D66165-501	D66166-501	D66165-502	D66166-502
BOXD946GZISSL 882974	882974	D66165-501	D66166-501	D66165-502	D66166-502

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

July 24, 2007

Revision Number:

00

Reason:

Originally Published PCN