

# Product Change Notification 111513 - 01

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2012. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skoool, the skoool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at http://www.intel.com/intel/legal/tmusage2.htm.



## **Product Change Notification**

Change Notification #: 111513 - 01

Change Title: Intel® Integrated RAID Module

RMS25PB080, RMS25PB040, RMT3PB080,

RMS25CB080, RMS25CB040, and RMT3CB080, PCN 111513-01, Product

Design, Hardware Design Change, Reason for Revision: Update Milestone, Pre Change TA

and PBA

Date of Publication: July 12, 2012

#### **Key Characteristics of the Change:**

Product Design

#### **Forecasted Key Milestones:**

Date Customer Must be Ready to Receive Post-Conversion Material: Aug 03, 2012

#### **Description of Change to the Customer:**

Reason for Revision: Update Milestone, Pre Change TA and PBA

Intel is implementing a printed circuit board (PCB) change to provide a long term solution for an issue with the Intel® RAID Smart Battery AXXRSBBU9 and Intel® RAID Maintenance Free Backup Unit AXXRMFBU2 cache backup solution. Please see Technical Advisory (TA-1005-01) for more details.

#### **Customer Impact of Change and Recommended Action:**

Intel recommends that the customer perform a standard level of evaluation as updated product become available.

#### **Products Affected / Intel Ordering Codes:**

| Pre Change<br>Product Code | Pre<br>Change<br>MM# | Pre<br>Change<br>TA | Pre<br>Change<br>PBA | Post Change<br>Product Code | Post<br>Change<br>MM# | Post<br>Change<br>TA | Post<br>Change<br>PBA |
|----------------------------|----------------------|---------------------|----------------------|-----------------------------|-----------------------|----------------------|-----------------------|
| RMS25PB080                 | 917056               | G34888-<br>503      | G27504-<br>503       | RMS25PB080                  | 923072                | G34888-<br>601       | G27504-<br>601        |
| RMS25PB040                 | 917078               | G34892-<br>503      | G45802-<br>503       | RMS25PB040                  | 923083                | G34892-<br>601       | G45802-<br>601        |
| RMT3PB080                  | 917079               | G34893-<br>503      | G45803-<br>503       | RMT3PB080                   | 923084                | G34893-<br>601       | G45803-<br>601        |
| RMS25CB080                 | 917084               | G34894-<br>503      | G35316-<br>503       | RMS25CB080                  | 923085                | G34894-<br>601       | G35316-<br>601        |

| Pre Change   | Pre    | Pre     | Pre     | Post Change         | Post   | Post    | Post    |
|--------------|--------|---------|---------|---------------------|--------|---------|---------|
| Product Code | Change | Change  | Change  | <b>Product Code</b> | Change | Change  | Change  |
|              | MM#    | TA      | PBA     |                     | MM#    | TA      | PBA     |
| RMS25CB040   | 917085 | G34895- | G41024- | RMS25CB040          | 923086 | G34895- | G41024- |
|              |        | 503     | 503     |                     |        | 601     | 601     |
| RMT3CB080    | 917086 | G34899- | G41025- | RMT3CB080           | 923087 | G34899- | G41025- |
|              |        | 503     | 503     |                     |        | 601     | 601     |

### **PCN Revision History:**

Date of Revision: **Revision Number:** Reason:

June 3, 2012 00 Originally Published PCN Update Milestone, Pre Change TA and PBA July 9, 2012 01