

Product Change Notification

Change Notification #: 114742 - 00

Change Title: Intel® Server Board S2600WT2R,

Intel® Server Board S2600WTTR

PCN 114742 - 00 Product Design

Replacement of components under RoHS

exemptions and updated

BIOS/ME/BMC/FRUSDR Firmware.

Date of Publication: June 30, 2016

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material: July 15, 2016

Description of Change to the Customer:

Intel is implementing the following changes on the Intel® Server Boards S2600WT2R and S2600WTTR:

- 1. Replacement of components containing substances listed under EU RoHS exemption 6(c), 7(c) and 15. All new components are identical in form factor and function to the replaced ones.
 - Components containing substances listed under EU RoHS exemption 7(a) are not affected.
- 2. Update of the System Firmware installed at the Factory:
 - a. Update the BIOS from revision R01.01.0014 to revision R01.01.0016.
 - b. Update the Manageability Engine (ME) firmware from revision 03.01.03.005 to revision 03.01.03.021.
 - c. Update the Integrated Baseboard Management Controller (BMC) firmware from revision 1.13.8932 to revision 01.43.9685.
 - d. Update the FRUSDR from revision 1.11 to revision 1.13

The system software update package, including the release notes for each, is available for download from http://www.intel.com/support. Please refer to the software release notes for a list of changes.

Customer Impact of Change and Recommended Action:

Intel does not expect any impact to customers from these changes, but encourages customers to understand the change and determine the impact on their applications. For that reason Intel recommends that the customer perform a standard level of evaluation. Customers can download and evaluate the latest BIOS/ME/Integrated BMC and FRUSDR release notes for more information at http://www.intel.com/support.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre TA#	Post TA#	Pre-PBA	Post-PBA
S2600WT2R	943786	H79749-002	H79749-003	H21573-366	H21573-371
S2600WTTR	943785	H79751-003	H79751-004	G92187-367	G92187-371

PCN Revision History:

Date of Revision: Revision Number: Reason:

June 30, 2016 00 Originally Published PCN



Product Change Notification

#114742 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com
Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com
Japan Email: jccb.ijkk@intel.com

 $\textbf{Copyright} \ \textcircled{\o} \ \textbf{Intel Corporation 2016.} \ \textbf{Other names and brands may be claimed as the property of others.}$

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skoool, the skoool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at http://www.intel.com/intel/legal/tmusage2.htm .