



# Product Change Notification

**Change Notification #: 119535-00**

**Change Title:** Select Intel® Ethernet Network and Server Adapters and Intel® Ethernet SFP+ SR Optics and QSFP+ LR Optics,  
PCN 119535-00, Product Discontinuance,  
End of life

**Date of Publication:** April 24, 2023

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

Last Product Discontinuance Order Date	July 24, 2023
Last Product Discontinuance Shipment Date	October 24, 2023

## Description of Change to the Customer:

The Intel SKUs listed in the products affected table will End of life.

## Customer Impact of Change and Recommended Action:

Customers should place their Last Time Orders by July 24, 2023, and delivery of all orders must be taken no later than October 24, 2023. The recommended replacement SKUs are noted within the affected products table within this PCN notice. If no replacement SKUs are noted, it means that there are no replacement parts available.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

## Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	Affected MM#	Recommended replacement Product Code	Recommended replacement MM#
Intel® Ethernet QSFP+ LR Optics, retail unit	E40GQSFPLR	933912	E40GQSFPSR	933911
Intel® Ethernet Server Adapter X710-DA2 for OCP, Retail Unit	X710DA2OCP	954745	XXV710DA2OCP1	959797
Intel® Ethernet Network Adapter XXV710-DA2 for OCP, retail unit	XXV710DA2OCP2	962202	XXV710DA2OCP1	959797
Intel® Ethernet Server Adapter X710-DA2 for OCP, Retail Unit	X710DA2OCP1	963638	XXV710DA2OCP1	959797
Intel® Ethernet Server Adapter X710-DA2 for OCP, OEM Gen	X710DA2OCP1G1P5	963726	XXV710DA2OCPG1	949035
Intel® Ethernet Network Adapter OCP3.0 X710-DA2, Retail Unit	X710DA2OCPV3	979095	X710DA2OCPV3G1P	979097

Intel® Ethernet Network Adapter OCP3.0 X710-DA4, Retail Unit	X710DA4OCPV3	979098	X710DA4OCPV3G1P	979099
Intel® Ethernet Network Adapter OCP3.0 I350-T4, Retail Unit	I350T4OCPV3	979127	I350T4OCPV3G1P5	979132
Intel® Ethernet SFP+ SR Optics, OEM Gen	E10GSFPSRG2P5	99AFL4	E10GSFPSRG1P5, E10GSFPSR	909923, 903239

## PCN Revision History:

**Date of Revision:**

April 24, 2023

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 119535-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)