



# Product Change Notification

**Change Notification #:** 115194 - 01  
**Change Title:** Selected Intel® Server Boards, Intel® Server Systems, Intel® Server Chassis & Intel® Storage Systems, PCN 115194-01, Product Discontinuance, End of Life,  
**Reason for Revision: Correction to Recommended Replacements Product Codes and MM#'s for Product Codes S1600JP4 and S1600JP2**  
**Date of Publication:** January 13, 2020

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	December 21, 2016
<b>Last Product Discontinuance Order Date:</b>	June 30, 2017
<b>Orders are Non-Cancelable and Non-Returnable After:</b>	March 31, 2017
<b>Last Product Discontinuance Shipment Date:</b>	October 31, 2017

## Description of Change to the Customer:

[Reason for Revision: Correction to Recommended Replacements Product Codes and MM#'s for Product Codes S1600JP4 and S1600JP2](#)

Intel is announcing the discontinuance of selected Intel® Server Boards, Intel® Server Systems, Intel® Server Chassis & Intel® Storage Systems as listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. Intel will discontinue builds on the LPDO date. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Deliveries must be accepted within 90 days from the LPDO date.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

## Engineering and Support Guidance for Discontinued Products:

1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g. to qualify new vendor due to a component EOL).
3. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

## Customer Impact of Change and Recommended Action:

Determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 Weeks.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

## Products Affected / Intel Ordering Codes:

Intel® Xeon E5-2600 Boards and Systems				
Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Server Board S2600CO4	BBS2600CO4	916033	DBS2600CW2R	943803
Intel® Server Board S2600CP2	DBS2600CP2	916040	DBS2600CW2R	943803
Intel® Server Board S2600CP4	DBS2600CP4	916041	DBS2600CW2R	943803
Intel® Server Board S2600GZ4	S2600GZ4	917968	S2600WT2R	943786
Intel® Server Board S2600GL4	S2600GL4	917969	S2600WT2R	943786
Intel® Server Board S2600COE	DBS2600COE	918728	DBS2600CW2R	943803
Intel® Server Board S1600JP4	BBS1600JP4	923163	<a href="#">DBS1200SPS</a>	<a href="#">944683</a>
Intel® Server Board S1600JP2	BBS1600JP2	923164	<a href="#">DBS1200SPS</a>	<a href="#">944683</a>
Intel® Server System R1304GZ4GC	R1304GZ4GC	916994	R1304WT2GSR	943892
Intel® Server System R1208GZ4GC	R1208GZ4GC	916995	R1208WT2GSR	943894
Intel® Server System R2208GZ4GC	R2208GZ4GC	917001	R2208WT2YSR	943827
Intel® Server System R2308GZ4GC	R2308GZ4GC	917004	R2308WTTYSR	943829
Intel® Server System P4308CP4MHGC	P4308CP4MHGC	918994	P4304XXMFEN2	936416
Intel® Server System R2304LH2HKC	R2304LH2HKC	919482	R2308WTTYSR	943829
Intel® Server System R2224GZ4GC4	R2224GZ4GC4	921971	R2224WTTYSR	943831
Intel® Server System R2312GZ4GC4	R2312GZ4GC4	921972	R2312WTTYSR	943830
Intel® Server System R1304JP4OC	R1304JP4OC	923165	R1304SPOSHBN	944471
Intel® Server System R1208JP4OC	R1208JP4OC	923166	R1208SPOSHOR	944477
Intel® Server System R1304JP4GS	R1304JP4GS	923168	R1304SPOSHBN	944471
Intel® Server System R2000LTMJC	R2000LTMJC	932725	R2208WTTYSR	943826

Intel® Xeon E5-2400 Boards and Systems				
Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Server Board S1400FP2	DBS1400FP2	920570	DBS2600CW2R	943803
Intel® Server Board S1400FP4	DBS1400FP4	920571	DBS2600CW2R	943803
Intel® Server Board S1400SP4	DBS1400SP4	920581	DBS1200SPS	944683
Intel® Server System R1304SP4SHOC	R1304SP4SHOC	920598	R1304SPOSHOR	944476

<b>Chassis and Storage Systems</b>				
<b>Product Name</b>	<b>Product Code</b>	<b>MM#</b>	<b>Recommended Replacement Product Code</b>	<b>Recommended Replacement MM#</b>
Intel® Server Chassis P4304XXSHDR	P4304XXSHDR	916171	P4000XXSFDR	944468
Intel® Server Chassis P4308XXMHGC	P4308XXMHGC	916320	P4304XXMFEN2	936416
Intel® Server Chassis P4308XXMHGN	P4308XXMHGN	916328	P4304XXMFEN2	936416
Intel® Server Chassis P4308XXMFEN	P4308XXMFEN	916337	P4304XXMFEN2	936416
Intel® Storage System JBOD2312S2SP	JBOD2312S2SP	927043	JBOD2312S3SP	939205
Intel® Storage System JBOD2224S2DP	JBOD2224S2DP	927045	N/A	N/A

### **PCN Revision History:**

**Date of Revision:**

December 21, 2016

January 13, 2020

**Revision Number:**

00

01

**Reason:**

Originally Published PCN

Correction to Recommended Replacements Product Codes and MM#'s for Product Codes S1600JP4 and S1600JP2



# Product Change Notification

## 115194 - 01

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2020. Other names and brands may be claimed as the property of others.

3D XPoint, ACEX, Altera, APEX, AnyWAN, Arria, Avalon, Axxia, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, CONVERGATE, Cyclone, Docea, eASIC, easicopy, Empirion, Flexpipe, Hyperflex, Intel, the Intel logo, Intel Adaptix, Intel Agilix, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Falcon, Intel Inside, the Intel Inside logo, Intel Nervana, Intel Optane, Intel RealSense, Intel Shooting Star, Intel Sirius, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Iris, Itanium, MAX, Movidius, Myriad, neon, Nios, OpenVINO, the OpenVINO logo, Pentium, Puma, Quark, Quartus, SICOFI, Simics, SMARTi, SoftSilicon, Sound Mark, StarPro, Stratix, the Stratix logo, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcende, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS® Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.