



Product Change Notification

109558 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109558 - 00
Change Title: SR1630BC, PCN 109558-00, Product Design, System Software and Documentation Update
Date of Publication: August 24, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 14, 2009
---	--------------

Description of Change to the Customer:

System Software programmed at the factory on the Intel(R) Server Board S5500BC used in the Intel(R) Server System SR1630BC is being updated:

- BIOS - update from R0025.1 to R0038 (See BIOS release notes for a list of the changes)
- BMC firmware - update from 00.28 to 00.40 (See BMC release notes for a list of the changes)
- FRUSDR - update from 08 to 14 (See FRUSDR release notes for a list of the changes)
- Intel(R) LAN Controller 82574L EEPROM is being updated to version 1.2 - This change disables WakeOnLAN when the 82574L is disabled in the Operating System

- Resource CD - Update from E40558-003 to E40558-005 - Updated drivers and documentation

- Intel(R) Server Management Software DVD - Update from 3.1 to 3.5.1 (See release notes for a list of the changes)

Customer Impact of Change and Recommended Action:

Intel does not expect any customer impact due to these changes. Please evaluate the software packages when made available. Intel recommends customers to understand these changes and determine impacts to their specific applications when the updated products become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SR1630BC	900773	2073-006	E25124-405	E32073-007	E25124-406
SR1630BCNA	901893	2073-006	E25124-405	E32073-007	E25124-406

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

August 24, 2009

Revision Number:

00

Reason:

Originally Published PCN