



Product Change Notification

Change Notification #: 119105-00
Change Title: Select Intel® Ethernet Network Adapters, PCN 119105-00, Product Design, Label OUI Block change and Label Update
Date of Publication: June 15, 2022

Key Characteristics of the Change:

Product Design, Label

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material	July 22, 2022
--	---------------

Description of Change to the Customer:

The Intel products listed in the product affected table below will undergo the following change:

- The current OUI block has hit the low watermark, the new OUI Block used will be EC-E7-A7.

As a result of this change, the PBA (printed board assembly) and TA (top assembly) numbers will roll as noted in the affected products table within this PCN notice. If the PBA/TA numbers are printed on any product or box labels, those will show the PBA/TA dash roll as well.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Customers can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected/Intel Ordering Codes:

Marketing Name	Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
Intel® Ethernet Converged Network Adapter X550-T2, 5 Pack	X550T2BLK	940136	H99164-003	H86377-006	H99164-004	H86377-007
Intel® Ethernet Converged Network Adapter X550-T2, Single Pack	X550T2	940128	H92776-003	H86377-006	H92776-004	H86377-007
Intel® Ethernet Server Adapter X710-DA2 for OCP, Retail Unit	X710DA2OCP	954745	J54442-003	J51959-004	J54442-004	J51959-005
Intel® Ethernet Network Adapter XXV710-DA2 for OCP, retail unit	XXV710DA2OCP2	962202	J75382-001	J60332-004	J75382-002	J60332-005
Intel® Ethernet Server Adapter X710-DA2 for OCP, Retail Unit	X710DA2OCP1	963638	J83255-002	J83809-002	J83255-003	J83809-003
Intel® Ethernet Server Adapter X710-DA2 for OCP, OEM Gen	X710DA2OCP1G1P5	963726	J83818-003	J83813-004	J83818-004	J83813-005
Intel® Ethernet Network Adapter OCP 3.0 X710-T2L, Retail Unit	X710T2LOCPV3	9999MJ	K64401-004	K58515-004	K64401-005	K58515-005
Intel® Ethernet Network Adapter OCP 3.0 X710-T2L, OEM Gen	X710T2LOCPV3G1P	9999MK	K58360-005	K31193-009	K58360-006	K31193-010
Intel® Ethernet Network Adapter OCP 3.0 X710-T4L, Retail Unit	X710T4LOCPV3	9999ML	K64404-002	K58564-002	K64404-003	K58564-003
Intel® Ethernet Network Adapter XXV710-DA2 for OCP, OEM Gen	XXV710DA2OCPG1T	999LWN	K63141-001	K64530-001	K63141-002	K64530-002

PCN Revision History:

Date of Revision:

June 15, 2022

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

119105-00

Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at www.intc.com.

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

Americas Contact: asm.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com