



Product Change Notification

108115 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108115 - 01
Change Title: S5000VCL; SR1530CL; SR1530HCL(S),
PCN 108115-01, Product Design, Update
BIOS, BMC and FRU/SDR, Reason for
Revision: To include systems affected by this
change
Date of Publication: August 14, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 11, 2008
---	--------------

Description of Change to the Customer:

Reason for Revision: To include systems affected by this change

The Intel(R) Server Board S5000VCL software is being updated to BIOS production 84(see BIOS release notes for details); BMC production version 62 (see BMC release notes for details); and FRU/SDR production version 18 (see FRU/SDR release notes for details)

These changes are to support the 45nm Intel(R) Xeon(R) Processors and the Closed Loop Thermal Throttling (CLTT) feature.

Customer Impact of Change and Recommended Action:

Customers are recommended to upgrade their software stack to the latest released versions although the new software will be "backwards compatible" for maintenance and older processor support. Intel does not anticipate any customer impact for this change. Evaluate when available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
BBS5000VCLSASR	892083	D69372-700	D24481-700	896204	D69372-701	D24481-701
BBS5000VCLR	892085	E14303-700	D41874-700	896205	E14303-701	D41874-701

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SR1530CLR	892052	E20937-002	D41874-700	E20937-003	D41874-701
SR1530CLRNA	892053	E20937-002	D41874-700	E20937-003	D41874-701
SR1530HCLR	892054	E20943-001	D41874-700	E20943-002	D41874-701
SR1530HCLRNA	892057	E20943-001	D41874-700	E20943-002	D41874-701
SR1530HCLSRNA	892047	E20944-001	D24481-700	E20944-002	D24481-701
SR1530HCLSR	892060	E20944-001	D24481-700	E20944-002	D24481-701

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

December 11, 2007

00

Originally Published PCN

August 14, 2008

01

To include systems affected by this change