



Product Change Notification

110055 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110055 - 01
Change Title: Intel® Storage Controller, Intel® Modular Server System MFSYS25, Intel® Modular Server System MFSYS35, PCN 110055-01, Product Material, Update Storage Control Module and Add to System Chassis, Reason for Revision: Additional supplies of the EOL NVRAM part have been acquired pushing out the cut in date.
Date of Publication: June 04, 2010

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 06, 2010
--	--------------

Description of Change to the Customer:

Reason for Revision: Additional supplies of the EOL NVRAM part have been acquired pushing out the cut in date.

An NVRAM part has gone end of life on the SCM PCB and is being replaced with a new part with similar functionality. The SCM PCB is being spun to accommodate the new part.

The updated SCM is being cut into both system chassis.

Customer Impact of Change and Recommended Action:

The updated SCM is being fully tested before release so Intel anticipates no impact to customers. No specific customer action is being recommended or required.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
AXXSCM3S	891831	E15895-006	D70737-410	AXXSCM3S	891831	E15895-007	D70737-500
MFSYS25	902318	D91400-XXX		MFSYS25	902318	D91400-YYY	
MFSYS35	902319	D91403-XXX		MFSYS35	902319	D91403-YYY	

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

May 21, 2010

00

Originally Published PCN

June 4, 2010

01

Additional supplies of the EOL
NVRAM part have been acquired
pushing out the cut in date.