



# Product Change Notification

## 113530 - 00

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

**Change Notification #: 113530 - 00**

**Change Title:            Boxed Intel® NUC Kit  
                              DN2820FYKH, Single Pack  
                              PCN 113530-00  
                              Product Design, Label  
                              BIOS Update and Add MAC  
                              Address Label**

**Date of Publication:    December 18, 2014**

## **Key Characteristics of the Change:**

Product Design

## **Forecasted Key Milestones:**

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jan 2, 2015
---	-------------

## **Description of Change to the Customer:**

1. The BIOS will be updated to version WYLPT10H.86A.0030. To access the release notes or get a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>
2. A MAC Address label will be added to the bottom cover. See below for pictures of the change. This label is a duplicate of the one already on the board.

For WYK SKU's:



For WYKH SKU's:



## Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate the new BIOS to ensure a smooth transition. Intel validation of a new board revision does not include testing with older versions of BIOS. This change is not expected to cause a change to the Microsoft Windows\* operating system's software driver stack. To access the release notes or get a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>.

These changes have been evaluated to ensure there is no quality, reliability, or functional implication to our customers. Intel is not recommending additional qualification of these changes on platforms received from Intel.

Intel will attempt to deplete pre-conversion material before shipping post-conversion material but there is a possibility of Intel shipping mixed inventory. Therefore, customers will need to manage and migrate to the post-conversion material as soon as possible.

Milestone dates are estimates and subject to change based on business and operational conditions.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change SA	Pre Change AA	Post Change SA	Post Change AA
BLKD34010WYB	931573		H14771-304		H14771-305
BOXD34010WYK	931574	H 14767-104	H14771-304	H14767-105	H14771-305
BOXD34010WYK1	931576	H14767-104	H14771-304	H14767-105	H14771-305
BOXD54250WYK	931577	H14752-104	H13922-304	H14752-105	H13922-305
BOXD54250WYK1	931578	H14752-104	H13922-304	H14752-105	H13922-305
BLKD54250WYB	931580		H13922-304		H13922-305
BOXD34010WYK2	931820	H14767-104	H14771-304	H16586-105	H14771-305
BOXD34010WYK3	931822	H14767-104	H14771-304	H14767-105	H14771-305
BOXD54250WYK2	931823	H14752-104	H13922-304	H14752-105	H13922-305
BOXD54250WYK3	931824	H14752-104	H13922-304	H14752-105	H13922-305
BOXD54250WYKH	932421	H25101-104	H13922-304	H25101-105	H13922-305
BOXD54250WYKH1	932422	H26245-104	H13922-304	H26245-105	H13922-305
BOXD54250WYKH2	932423	H26246-104	H13922-304	H26245-105	H13922-305
BOXD54250WYKH3	932424	H26247-104	H13922-304	H26247-105	H13922-305
BOXD34010WYKH	932425	H14767-104	H14771-304	H25115-105	H14771-305
BOXD34010WYKH1	932426	H26248-104	H14771-304	H26248-105	H14771-305
BOXD34010WYKH2	932427	H26249-104	H14771-304	H26249-105	H14771-305
BOXD34010WYKH3	932428	H26250-104	H14771-304	H26250-105	H14771-305

## PCN Revision History:

**Date of Revision:**  
December 18, 2014

**Revision Number:**  
00

**Reason:**  
Originally Published PCN