



Product Change Notification

106535 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 106535 - 01
Change Title: SR1500, SR2500, SR1550, Class 2, PCN 106535-01, Product Design, Bridgeboard retention change, CPU Air Duct change, Reason for Revision: Adding CPU Air Duct change and adding affected products
Date of Publication: August 18, 2006

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 08, 2006
---	--------------

Description of Change to the Customer:

Reason for Revision: Adding CPU Air Duct change and adding affected products

Change Bridge Board from -301 to -401

Extend the height of the bridge board and augment the retention features to improve wire bale retention reliability.

(change only affects systems and electrical spare kits)

Remove Foam Gaskets from CPU Air Duct

After further testing, the gaskets on top of the 1U CPU air duct were found to be unnecessary.

(change only affects SR1500 and SR1550 systems and chassis spare kits)

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
ASR1500CHSPR	880907	880907	D47693-002	D47693-003		
ASR1500EESPR	880900	880900	D47695-002	D47695-003	D25543-301	D25543-401
ASR1550CHSPR	881679	881679	D48157-001	D48157-002		
ASR1550EESPR	881678	881678	D48158-001	D48158-002	D25543-301	D25543-401
ASR2500EESPR	881265	881265	D43775-003	D43775-004	D25543-301	D25543-401
FALBRIDGE	880519	880519	D43780-002	D43780-003	D25543-301	D25543-401
SR1500	881037	881037	D47572-002	D47572-003	D25543-301	D25543-401

Affected Product Code	Pre-Change MM#	Post-Change MM#	Pre-Change TA	Post-Change TA	Pre-Change Subassembly	Post-Change Subassembly
SR1500NA	881460	881460	D47572-002	D47572-003	D25543-301	D25543-401
SR1550	881737	881737	D48156-001	D48156-002	D25543-301	D25543-401
SR1550NA	881752	881752	D48156-001	D48156-002	D25543-301	D25543-401
SR2500	881105	881105	D43689-003	D43689-004	D25543-301	D25543-401
SR2500NA	881461	881461	D43689-003	D43689-004	D25543-301	D25543-401

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

July 17, 2006

00

Originally Published PCN

August 18, 2006

01

Adding CPU Air Duct change and adding affected products