



# Product Change Notification

## 108413 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jcb.ijkk@intel.com](mailto:jcb.ijkk@intel.com)

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 108413 - 01  
**Change Title:** D201GLY, PCN 108413-01, Product Design, DIMM connector change, Reason for Revision: Delay heatsink change  
**Date of Publication:** May 28, 2008

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jun 19, 2008
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Delay heatsink change

The DIMM connectors are being replaced with enhanced versions from the same vendors.

Change of heatsink is being delayed to a future date.

## Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers.

Intel is not recommending additional qualification of these changes on platforms received from Intel.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
LAD201GLYLT	887701	D78099-400	D78099-401
LAD201GLYL	887702	D76864-400	D76864-401
BLKD201GLYL	887958	D81205-400	D81205-401
BOXD201GLYL	887961	D81205-400	D81205-401

## PCN Revision History:

Date of Revision:	Revision Number:	Reason:
April 23, 2008	00	Originally Published PCN
May 28, 2008	01	Delay heatsink change

