



# Product Change Notification

## 113047 - 01

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

**A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.**

**Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.**

**The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.**

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

**Copyright © Intel Corporation 2013. Other names and brands may be claimed as the property of others.**

**BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.**

**Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.**



# Product Change Notification

**Change Notification #:** 113047 - 01  
**Change Title:** Selected Intel® Server Boards and Intel® Server Systems  
 PCN 113047-01, Product Discontinuance End of Life  
**Reason for Revision: Products DBS1400FP2, R1208BB4GS9 and R1304BB4GS9 will not end of life at this time.**

**Date of Publication:** July 30, 2014

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Last Product Discontinuance Order Date *:</b>	Dec 03, 2014
<b>Last Product Discontinuance Shipment Date:</b>	Mar 03, 2015

*\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.*

## Description of Change to the Customer:

**Reason for Revision: Products DBS1400FP2, R1208BB4GS9 and R1304BB4GS9 will not end of life at this time**

Intel is announcing the discontinuance of Select Intel® Server Boards and Intel® Server Systems products listed in the "Products Affected/Intel Ordering Codes" table below.

<b>Date (example)</b>	<b>Definition</b>
<b>June 6, 2014</b>	<b>PDA: Product Discontinuance Announced.</b>
	Business as usual. Distributor stock rotation returns will be accepted up until the NCNR date.
<b>Sept 4, 2014</b>	<b>NCNR: Non-Cancelable and Non-Returnable date.</b>
	Intel will make best efforts to support all orders placed between NCNR and FCFS. Deliveries must be accepted within 90 days from the FCFS date.
<b>Dec 3, 2014</b>	<b>FCFS: First Come First Served Order Date</b>
	Existing inventory is still orderable, under NCNR terms, and will be filled on a <b>first come first served</b> basis. Intel will discontinue product builds on the FCFS date. Deliveries must be accepted within 90 days.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgment, or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

The products listed in the "Products Affected/Intel Ordering Codes" table below, have been discontinued, and will be unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Key Milestones" above) OR as soon as current inventories are depleted. All orders will be filled on a first-come, first-served basis. For applicable replacement product(s), please see the "Replacement Product" column in table below.

### **Engineering and Support Guidance for Discontinued Products:**

1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g. to qualify new vendor due to a component EOL).
3. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

### **Customer Impact of Change and Recommended Action:**

Determine your remaining demand for these products and/or evaluate additional sources (if applicable).

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

## Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#	Recommended Replacement Product Code	Recommended Replacement MM#
Intel® Server Board S2400LP	BBS2400LP	919030	BBS2600JF	917760
Intel® Server Board S2400SC2	BBS2400SC2	919821	DBS2400SC2	919820
Intel® Server Board S1400FP2	BBS1400FP2	920572	DBS1400FP4	920571
Intel® Server Board S1400FP4	BBS1400FP4	920573	DBS1400FP4	920571
Intel® Server Board S1400SP2	DBS1400SP2	920580	DBS1400SP4	920581
Intel® Server Board S1400SP2	BBS1400SP2	920582	DBS1400SP4	920581
Intel® Server Board S1400SP4	BBS1400SP4	920583	DBS1400SP4	920581
Intel® Server System P4216IP4LHJC	P4216IP4LHJC	916059	P4308IP4LHJC	916064
Intel® Server System R2308BB4GC	R2308BB4GC	918909	R1304BB4DC	918884
Intel® Server System R2208IP4LHPC	R2208IP4LHPC	919047	R2224IP4LHPC9	925547
Intel® Server System R2308SC2SHFN	R2308SC2SHFN	919783	DBS2400SC2	919820
Intel® Server System R2312SC2SHGR	R2312SC2SHGR	919785	DBS2400SC2	919820
Intel® Server System P4304SC2SFEN	P4304SC2SFEN	919800	P4308SC2MHGC	919789
Intel® Server System R1304SP2SHBN	R1304SP2SHBN	920591	R1304SP4SHOC	920598
Intel® Server System R2312BB4GS9	R2312BB4GS9	922002	R1304BB4DC	918884
Intel® Server System R2208BB4GS9	R2208BB4GS9	922003	R1208BB4DC	918887
Intel® Server System R1208GZ4GS9	R1208GZ4GS9	922760	R1208GZ4GC	916995
Intel® Server System R1304JP4TC	R1304JP4TC	923170	R1304RPSSFBN	930699
Intel® Server System R1208JP4TC	R1208JP4TC	923172	R1208RPMSHOR	927917

## Product Affected / Intel Order Code(s) removed from PCN:

Product Name	Product Code	MM#
Intel® Server Board S1400FP2	DBS1400FP2	920570
Intel® Server System R1208BB4GS9	R1208BB4GS9	921999
Intel® Server System R1304BB4GS9	R1304BB4GS9	922000

## PCN Revision History:

### Date of Revision:

June 06, 2014

**July 30, 2014**

### Revision Number:

00

**01**

### Reason:

Originally Published PCN

**Products DBS1400FP2, R1208BB4GS9 and R1304BB4GS9 will not end of life at this time.**