



Product Change Notification

107606 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107606 - 00
Change Title: Intel PRO/100 S Desktop Adapter (MacKenzie), PRO/100 S Server Adapter (SouthBend), PRO/100 M Desktop Adapter (Dayville), PRO/100 S Dual Port Server Adapter (Gainesville) & PRO/1000 MT Dual Port Server Adapter (Double Barrow)

PCN 107606-00

Manufacturing Site

Manufacturing Site Change from Suzhou, People's Republic of China to Penang, Malaysia

Date of Publication: June 28, 2007

Key Characteristics of the Change:

Manufacturing Site

Forecasted Key Milestones:

	MacKenzie, SouthBend & Dayville	Gainesville	Double Barrow
Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 11, 2007	Jun 18, 2007	Jun 25, 2007

Description of Change to the Customer:

The Intel PRO/100 S Desktop Adapter (MacKenzie), PRO/100 S Server Adapter (SouthBend), PRO/100 M Desktop Adapter (Dayville), PRO/100 S Dual Port Server Adapter (Gainesville) & PRO/1000 MT Dual Port Server Adapter (Double Barrow) products as shown in the affected products table within this PCN notification will undergo the following change:

Intel Corporation is consolidating the assembly of its Intel PRO Network Adapters into one contract manufacturing site. Adapters are currently manufactured in two Intel qualified facilities, one in Penang, Malaysia and one in Suzhou, People's Republic of China.

Intel will transfer and consolidate its adapter products into the Intel qualified facility located in Penang, Malaysia. The Penang facility was qualified in 2001 to manufacture adapter products, and it currently manufactures adapters with equivalent product technology.

There will be no change to the product except the location it is manufactured, and the identification that the product is now "Made in Malaysia" vs. the older "Made in China".

Customer Impact of Change and Recommended Action:

- There will be no change to Form, Fit or Function, except reference to the manufacturing location as mentioned above.
- The implementation date for all changes, on each SKU, will occur via a staggered implementation approach.
- The Customer Ready to Receive dates, per SKU, are noted within the Forecasted Key Milestone table within this PCN notification.
- Customers should expect to receive mixed inventory on all products, until current inventory levels are depleted.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	MM#
PRO/100 S Server Adapter (SouthBend) Retail single	PILA8470C3	832702
PRO/100 S Server Adapter (SouthBend) Retail 5 pak	PILA8470C3PAK5	832704
PRO/100 M Desktop Adapter (Dayville) Retail blk 20 pak	PILA8460MBLK20	847578
PRO/100 M Desktop Adapter (Dayville) Retail single	PILA8460M	854613
Intel PRO/100 S Desktop Adapter (MacKenzie) Retail blk 20 pak	PILA8460C3BLK	870508
Intel PRO/100 S Desktop Adapter (MacKenzie) Retail Japan single	PILA8460C3J	838010
Intel PRO/100 S Desktop Adapter (MacKenzie) Retail single	PILA8460C3	832696
PRO/100 S Dual Port Server Adapter (Gainesville) Retail single	PILA8472C3	829938
PRO/100 S Dual Port Server Adapter (Gainesville) Retail 5 pak	PILA8472C3PAK5	829939
PRO/1000 MT Dual Port Server Adapter (Double Barrow) Retail single	PWLA8492MT	844143
PRO/1000 MT Dual Port Server Adapter (Double Barrow) Retail 5 pak	PWLA8492MTBLK5	847743

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

June 28, 2007

Revision Number:

00

Reason:

Originally Published PCN