



# Product Change Notification

**Change Notification #:** 114748 - 00  
**Change Title:** Select Intel® Chipset and IA Products  
 PCN 114748-00,  
 Product Discontinuance

**Date of Publication:** July 15, 2016

## Key Characteristics of the Change:

Product Discontinuance

## Forecasted Key Milestones:

<b>Product Discontinuance Program Support Begins:</b>	July 15, 2016
<b>Last Product Discontinuance Order Date:</b>	July 21, 2017
<b>Orders are Non-Cancelable and Non-Returnable After:</b>	July 21, 2017
<b>Last Product Discontinuance Shipment Date:</b>	January 19, 2018

## Description of Change to the Customer:

The product listed in the "Products Affected/Intel Ordering Codes" table below, has been discontinued, and will be unavailable for additional orders after the "Last Product Discontinuance Order Date" (see "Key Milestones" above) OR as soon as current inventories are depleted. All orders will be filled on a first-come, first-served basis.

## Customer Impact of Change and Recommended Action:

Please determine your remaining demand and place your "Last Product Discontinuance Orders" in accordance with the "Key Milestones" listed above. Orders are non-cancelable and non-returnable after July 21, 2017.

## Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#
Intel® 82GS45 Graphics and Memory Controller Hub	AC82GS45	S LB92	898196
Intel® 82GM45 Graphics and Memory Controller Hub	AC82GM45	S LB94	898200
Intel® 82GL40 Graphics and Memory Controller Hub	AC82GL40	S LB95	898201
Intel® Xeon® Processor E5220	AT80573QJ0536M	S LBAT	898613
Intel® Xeon® Processor E5240	AT80573QJ0806M	S LBAW	898614
Intel® 82G45 Graphics and Memory Controller Hub	AC82G45	S LB84	898624
Intel® 82Q45 Graphics and Memory Controller Hub	AC82Q45	S LB8A	898631
Intel® 82G41 Graphics and Memory Controller Hub	AC82G41	S LGQ3	902020
Intel® Xeon® Processor EC5539	AT80612003861AB	S LBWL	907835
Intel® Pentium® Processor 1405	CM8062001093700	S R0M7	919378

## PCN Revision History:

<b>Date of Revision:</b> July 15, 2016	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
---	-------------------------------	--



# Product Change Notification

## 114748 - 00

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.