



Product Change Notification

110890 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110890 - 00
Change Title: Intel® 5100 Memory Controller Hub (MCH), Intel® 82801FB I/O Controller Hub (ICH6), Intel® Celeron® M Processors 530, 550, ULV 573 , Intel® Pentium® III Processors, PCN 110890-00, Product Discontinuance
Date of Publication: July 28, 2011

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Product Discontinuance Program Support Begins:	Jul 28, 2011
Last Product Discontinuance Order Date:	Jul 30, 2012
Orders are Non-Cancelable and Non-Returnable After:	Jul 30, 2012
Last Product Discontinuance Shipment Date:	Jan 28, 2013

Description of Change to the Customer:

Due to a shift in demand to other products, Intel Corporation is announcing the discontinuance of the products listed in the "Products Affected/Intel Ordering Codes" table below.

Customer Impact of Change and Recommended Action:

Please determine your remaining demand and place your "Last Product Discontinuance Orders" in accordance with the "Key Milestones" listed above. Orders are non-cancelable and non-returnable after July 30, 2012.

Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#
Mobile Intel® Celeron® Processor	RJ80530MZ733256S L6B4	S L6B4	846832
Intel® Pentium® III Processor	RK80530KZ017512S L6BY	S L6BY	847862
Intel® Pentium® III Processor	RJ80530KZ933512S L69K	S L69K	849162
Mobile Intel® Pentium® 4 Processor	RH80532GC029512S L6V6	S L6V6	852229
Mobile Intel® Celeron® Processor	RJ80530MZ001256S L798	S L798	857027
Mobile Intel® Celeron® Processor	RH80532NC009256S L7MG	S L7MG	862086
Mobile Intel® Celeron® Processor	NK80530MZ733256S L7UH	S L7UH	863864
Intel® 82801FB I/O Controller Hub (ICH6)	FW82801FB S L7Y5	S L7Y5	865377
Intel® Xeon® Processor LV 5128	HH80556JH0364M S L9XA	S L9XA	887535
Intel® 5100 Memory Controller Hub (MCH)	QG5100MCH 891936		891936
Intel® Celeron® Processor 550	LE80537NE0411M S LALD	S LALD	892700
Intel® Celeron® M Processor 530	LE80537NE0301M S LGFY	S LGFY	899899
Intel® Celeron® Processor ULV 573	LE80537VE001512S LGMV	S LGMV	901266

PCN Revision History:

Date of Revision:

July 28, 2011

Revision Number:

00

Reason:

Originally Published PCN