



# Product Change Notification

## 109889 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109889 - 01  
**Change Title:** D510MO/V, D410PT, and D410PTL/W, PCN 109889-01, Product Design, BIOS updates, Reason for Revision: Correction on BIOS revision  
**Date of Publication:** March 30, 2010

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Apr 15, 2010
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Correction on BIOS revision

Intel has implemented the following changes:

1. D510MO/V BIOS update from version MOPNV10J.86A.0154 to MOPNV10J.86A.0175
2. D410PT BIOS update from version MOPNV10N.86A.0159 to MOPNV10N.86A.0171
3. D410PTL/W BIOS update from version MOPNV10N.86A.0159 to MOPNV10N.86A.0171

To access the release notes or a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>

## Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS. This change is not expected to cause a change to the Microsoft Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Post Change AA
BOXD510MO 903640	903640	E76523-401	E76523-402
BLKD510MO 903641	903641	E76523-401	E76523-402
LAD510MO 903642	903642	E76525-401	E76525-402
LAD510MOV 903643	903643	E67982-401	E67982-402

BOXD410PT 903646	903646	E76528-402	E76528-403
BLKD410PT 903647	903647	E76528-402	E76528-403
LAD410PT 903648	903648	E66175-404	E66175-405
LAD410PTL 904632	904632	E80287-300	E80287-301
LAD410PTLW 905660	905660	E86257-300	E86257-301
BLKD410PTL 905661	905661	E86256-300	E86256-301

### Reference Documents / Attachments:

**Document:** **Location #:**

### PCN Revision History:

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
March 23, 2010	00	Originally Published PCN
March 30, 2010	01	Correction on BIOS revision