



# Product Change Notification

**Change Notification #:** 114391 - 00  
**Change Title:** Intel® Server Board S2600CP4,  
Intel® Server Board S2600CP2,  
Intel® Server Board S2600COE,  
Intel® Server Board S2600CO4,  
Intel® Server Board S2600IP,  
PCN 114391-00, Label,  
Update PBA, Pretty Box and Outer Carton  
Labels  
**Date of Publication:** July 11, 2016

## Key Characteristics of the Change:

Label

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material *:</b>	July 12, 2016
---	---------------

\* Intel appreciates the customer's desire to receive the latest revision of products. However, Intel manages inventory on a first in first out (FIFO) basis at the MM# level. Subsequently, customer requests for a specific revision of material (below the MM#) will not be supported by Intel.

## Description of Change to the Customer:

Intel is implementing the following changes on the Intel® Server Board S2600CP2, Intel® Server Board S2600CP4, Intel® Server Board S2600COE, Intel® Server Board S2600CO4 and Intel® Server Board S2600IP:

1. Change C-Tick to RCM logo, remove J-Std 609 logo and update Canada ICES logo on the Pretty Box and Outer Carton Label.



Figure-1: Pretty Box Label Pre-Change



Figure-2: Pretty Box Label Post-Change

2. Change the C-Tick logo to RCM logo on the Printed Board Assembly by using a small label



Figure-3: PBA Label Pre-Change



Figure-4: PBA Label Post-change

**Customer Impact of Change and Recommended Action:**

Intel does not expect any impact to customers from these changes, but encourages customers to understand the change and determine the impact on their applications.

**Products Affected / Intel Ordering Codes:**

Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
DBS2600CP2	916040	G41269-506	G50768-511	G41269-507	G50768-512
DBS2600CP4	916041	G41273-506	E99552-511	G41273-507	E99552-512
SE99552	938054	G48804-506	E99552-511	G48804-507	E99552-512
DBS2600COE	918728	G50187-206	G29920-209	G50187-207	G29920-210
BBS2600CO4	916033	G50188-207	G35870-208	G50188-208	G35870-209
SG20993Z	936989	G89182-351	G20993-351	G89182-352	G20993-352

**PCN Revision History:**

**Date of Revision:**  
July 11, 2016

**Revision Number:**  
00

**Reason:**  
Originally Published PCN



# Product Change Notification

## #114391 - 00

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific/PRC Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm> .