



# Product Change Notification

**Change Notification #:** 117066- 04

**Change Title:** Intel® Server Chassis Hot Swap Drive Kit FUP4X35HSDK,  
Intel® Server Chassis Electrical Maintenance Kit FUPMESK,  
Intel® Server Fixed Fan Spare Kit FUPMNHFANPCI,  
Intel® Server Fixed Fan Spare Kit FUPNHFANCPU,  
Intel® Server Electrical Spare Kit FUPSESK,  
Intel® Server System Fan Kit FUPSNHFANE3,  
Intel® Server Trusted Platform Module AXXTPME6,  
Intel® Server Hot-swap Backplane Drive Cage Kit FUP8X25S3NVDK,  
Intel® Server Omni-Path Host Fabric Interface Adapter AHWKPTP100HF,  
Intel® Server 2U Bezel A2UBEZEL,  
Intel® Server Bridge Board AHWKPTP12GBGB,  
Intel® Server Bridge Board AHWKPTP12GBGBIT,  
Intel® Server Bridge Board AHWKPTP12GBGBR5,  
Intel® Server Breakout Board AHWKPTPBOB,  
Intel® Server Passive Heat-Sink AUPCWPBTP,  
Intel® Server I/O Module AXX1FDRIBIOM,  
Intel® Server I/O Module AXX2FDRIBIOM,  
Intel® Server Riser Card AXXKPTPIOM,  
Intel® Server Riser Card XXKPTPM2IOM,  
Intel® Server Premium Rail AXXPRAIL,  
Intel® Server Premium Rail AXXPRAIL755,

**Intel® Server Trusted Platform Module  
AXXTPME5,  
Intel® Server Trusted Platform Module  
AXXTPME7,  
Intel® Server Custom Premium Rail  
EXX1U2URAILS2,  
Intel® Server Riser Card F1UL16RISER2,  
Intel® Server Spare Node Power Board  
FH2000NPB2,  
Intel® Server Spare Node Power Board  
FH2000NPB24,  
Intel® Server Backplane FHW16X25HS12G,  
Intel® Server Riser Card FHW1U16RISER2,  
Intel® Server Backplane FHW24X25HS12G,  
Intel® Server Bridge Board FHWKPTPBGGB,  
Intel® Server Bridge Board  
FHWKPTPBGGB24,  
Intel® Server Hot-Swap Drive Carrier  
FXX25HSCAR,  
Intel® Server Hot-Swap Drive Carrier  
FXX35HSADPB,  
Intel® Server Heat Sink FXXCA84X106HS,  
Intel® Server Heat Sink FXXCA91X91HS,  
Intel® Server Heat Sink FXXEA84X106HS,  
Intel® Server Heat Sink FXXEA91X91HS2,  
Intel® Server ODD Bay Bracket Kit  
AXXSSDODDKIT,  
Intel® Server Cable Kit  
AXXCBLXPBHDMS,  
Intel® Server Cable Kit AXXCBL950HDMS,  
Intel® Server Cable Kit AXXCBL875HDMS,  
Intel® Server Cable Kit AXXCBL800HDMS,  
Intel® Server Cable Kit AXXCBL730MSMS,  
Intel® Server Cable Kit AXXCBL730HDMS,  
Intel® Server Cable Kit AXXCBL650MSMS,  
Intel® Server Cable Kit AXXCBL585HDMR,  
Intel® Server Cable Kit AXXCBL1UHRHD,  
Intel® Server Rear Hot-swap Dual Drive  
A2UREARHSDK,**

**Intel® Server Passive Airduct Kit  
AWTCOPRODUCT,  
Intel® Server ODD Bay Bracket Kit  
AXXSSDODDKIT,  
Intel® Server Switch Add-in Card  
AXX4PX8HDAIC,  
Intel® Server Hot-swap Backplane  
A2U44X25NVMEDK2,  
Intel® Server Hot-swap Backplane  
FXX8X25S3HSBP,  
Intel® Server Hot-swap Backplane  
F2U12X35S3HSBP,  
Intel® Server Hot-swap Drive Cage  
A2U44X25NVMEDK,  
Intel® Server Hot-swap Drive Cage  
A2U8X25S3HSDK,  
Intel® Server Hot-swap Drive Cage  
A2U8X35S3HSDK,  
Intel® Server Hot-swap Drive Cage  
A2U8X25S3DPDK,  
Intel® Server Hot-swap Backplane  
F1U8X25S3HSBP,  
Intel® Server Switch Riser Card  
A1U2PXR3HDAIC,  
Intel® Server Hot-swap Backplane  
A1U44X25NVMEDK,  
Intel® Server Bezel A1UBEZEL,  
Intel® Server ODD Bay Bracket Kit  
AXXSSDODDKIT,  
Intel® Server I/O Module  
AXX4P1GBPWLIOM,  
Intel® Server I/O Module  
AXX10GBTWLIOM3,  
Intel® Server I/O Module  
AXX10GBNIAIOM,  
Intel® Server I/O Module  
AXX10GBTWLHW3,  
Intel® Server Backplane FUP4X35S3HSBP,  
Intel® Server Backplane FR1304S3HSBP2,**

**Intel® Server Hot-Swap Drive Carrier  
FXX35HSCAR,  
Intel® Server Hot-Swap Drive Carrier  
FXX25HSCAR2,  
Intel® Spare SAS Cable Kit FR130412GCBL,  
PCN 117066-04,  
Product Discontinuance Announcement,  
End of Life,  
[Reason for Revision: Removing Intel® Kit of  
Serial Port DB9 Adapter AXXRJ45DB93](#)**

**Date of Publication:** July 31, 2020

**Key Characteristics of the Change:**

Product Discontinuance

**Forecasted Key Milestones:**

<b>Product Discontinuance Program Support Begins:</b>	July 19, 2019
<b>Last Product Discontinuance Order Date:</b>	July 5, 2020
<b>Last Product Discontinuance Shipment Date:</b>	October 5, 2020
<b>Orders for Discontinued Products Become Non-Cancelable:</b>	April 5, 2020

**Description of Change to the Customer:**

**[Reason for Revision: Removing Intel® Kit of Serial Port DB9 Adapter AXXRJ45DB93](#)**

Intel is announcing the discontinuance of the Intel® Server Spare kit listed in the "Products Affected/Intel Ordering Codes" table below.

Intel will make best efforts to support all orders placed between the Non-Cancelable and Non-Returnable (NCNR) and the Last Product Discontinuance Order (LPDO) dates. Intel will discontinue builds on the LPDO date. After the LPDO date existing inventory is still orderable, under NCNR terms, and will be filled on a first come first served basis. Deliveries must be accepted within 90 days from the LPDO date.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgement or Distributor agreements.

Intel reserves the right to change the products because of material source restriction.

## Engineering and Support Guidance for Discontinued Products:

1. No new OS, peripheral or adaptor validation is planned during the extended life period. The THOL, supported processor and tested memory lists are frozen at PDA.
2. No new features enhancements should be expected, however ECOs may be required during the extended life period to maintain supply lines (e.g. to qualify new vendor due to a component EOL).
3. Intel will provide reasonable commercial efforts in debugging issues during the warranty period for the product after the PDA date has passed. Fixes cannot be committed, but Intel will endeavor to provide reasonable workarounds for the product.

## Customer Impact of Change and Recommended Action:

Determine your remaining demand for this product and/or evaluate additional sources (if applicable).

Lead-times on products with announced product discontinuance can typically stretch to 12 weeks and volumes are not buffered during the PDA period. Please work with your Intel representative on your quarterly demand forecast in order to reduce lead-times to 2-4 Weeks.

Please contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Milestone dates are estimates and subject to change based on business and operational conditions.

## Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	MM#
Intel® Server Chassis Hot Swap Drive Kit	FUP4X35HSDK	911885
Intel® Server Chassis Electrical Maintenance Kit	FUPMESK	915653
Intel® Server Fixed Fan Spare Kit	FUPMNHFANPCI	919575
Intel® Server Fixed Fan Spare Kit	FUPNHFANCPU	919572
Intel® Server Electrical Spare Kit	FUPSESK	912774
Intel® Server System Fan Kit	FUPSNHFANE3	912772
Intel® Server Trusted Platform Module	AXXTPME6	947921
Intel® Server Hot-swap Backplane Drive Cage Kit	FUP8X25S3NVDK	936426
Intel® Server Omni-Path Host Fabric Interface Adapter	AHWKPTP100HF	949054
Intel® Server 2U Bezel	A2UBEZEL	918086
Intel® Server Bridge Board	AHWKPTP12GBGB	935580
Intel® Server Bridge Board	AHWKPTP12GBGBIT	949475
Intel® Server Bridge Board	AHWKPTP12GBGBR5	937453
Intel® Server Breakout Board	AHWKPTPBOB	936274
Intel® Server Passive Heat-Sink	AUPCWBPBP	936421
Intel® Server I/O Module	AXX1FDRIBIOM	918607
Intel® Server I/O Module	AXX2FDRIBIOM	920627
Intel® Server Riser Card	AXXKPTPIOM	935524
Intel® Server Riser Card	AXXKTPM2IOM	943483
Intel® Server Premium Rail	AXXPRAIL	924417
Intel® Server Premium Rail	AXXPRAIL755	924418
Intel® Server Trusted Platform Module	AXXTPME5	919737
Intel® Server Trusted Platform Module	AXXTPME7	947922
Intel® Server Custom Premium Rail	EXX1U2URAILS2	942266
Intel® Server Riser Card	F1UL16RISER2	934884
Intel® Server Spare Node Power Board	FH2000NPB2	935574
Intel® Server Spare Node Power Board	FH2000NPB24	943480
Intel® Server Backplane	FHW16X25HS12G	935573
Intel® Server Riser Card	FHW1U16RISER2	935565
Intel® Server Backplane	FHW24X25HS12G	943481

<b>Marketing Name</b>	<b>Product Code</b>	<b>MM#</b>
Intel® Server Bridge Board	FHWKPTPBGB	935575
Intel® Server Bridge Board	FHWKPTPBGB24	943482
Intel® Server Hot-Swap Drive Carrier	FXX25HSCAR	918807
Intel® Server Hot-Swap Drive Carrier	FXX35HSADPB	912771
Intel® Server Heat Sink	FXXCA84X106HS	918318
Intel® Server Heat Sink	FXXCA91X91HS	918250
Intel® Server Heat Sink	FXXEA84X106HS	918321
Intel® Server Heat Sink	FXXEA91X91HS2	937228
Intel® Server ODD Bay Bracket Kit	AXXSSDODDKIT	935065
Intel® Server Cable Kit	AXXCBLEXPDMMS	937127
Intel® Server Cable Kit	AXXCBL950HDMS	937131
Intel® Server Cable Kit	AXXCBL875HDMS	937130
Intel® Server Cable Kit	AXXCBL800HDMS	937309
Intel® Server Cable Kit	AXXCBL730MSMS	921049
Intel® Server Cable Kit	AXXCBL730HDMS	927238
Intel® Server Cable Kit	AXXCBL650MSMS	918376
Intel® Server Cable Kit	AXXCBL585HDMR	937315
Intel® Server Cable Kit	AXXCBL1UHRHD	937311
Intel® Server Rear Hot-swap Dual Drive	A2UREARHSDK	934976
Intel® Server Passive Airduct Kit	AWTCOPRODUCT	934988
Intel® Server ODD Bay Bracket Kit	AXXSSDODDKIT	935065
Intel® Server Switch Add-in Card	AXX4PX8HDAIC	947923
Intel® Server Hot-swap Backplane	A2U44X25NVMEDK2	947924
Intel® Server Hot-swap Backplane	FXX8X25S3HSBP	934890
Intel® Server Hot-swap Backplane	F2U12X35S3HSBP	934893
Intel® Server Hot-swap Drive Cage	A2U44X25NVMEDK	936253
Intel® Server Hot-swap Drive Cage	A2U8X25S3HSDK	935066
Intel® Server Hot-swap Drive Cage	A2U8X35S3HSDK	936191
Intel® Server Hot-swap Drive Cage	A2U8X25S3DPDK	935067
Intel® Server Hot-swap Backplane	F1U8X25S3HSBP	934888
Intel® Server Switch Riser Card	A1U2PXR3HDAIC	984450
Intel® Server Hot-swap Backplane	A1U44X25NVMEDK	936251
Intel® Server Bezel	A1UBEZEL	917983
Intel® Server ODD Bay Bracket Kit	AXXSSDODDKIT	935065
Intel® Server I/O Module	AXX4P1GBPWL IOM	917911
Intel® Server I/O Module	AXX10GBTWLIOM3	941869
Intel® Server I/O Module	AXX10GBNIAIOM	917905
Intel® Server I/O Module	AXX10GBTWLHW3	941868
Intel® Server Backplane	FUP4X35S3HSBP	936423
Intel® Server Backplane	FR1304S3HSBP2	947357
Intel® Server Hot-Swap Drive Carrier	FXX35HSCAR	936192
Intel® Server Hot-Swap Drive Carrier	FXX25HSCAR2	937542
Intel® Spare SAS Cable Kit	FR130412GCBL	943591

## PCN Revision History:

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
July 19, 2019	00	Originally Published PCN
August 6, 2019	01	Includes the Intel® Kit of Serial Port DB9 Adapters in PCN
September 16, 2019	02	Remove the Intel® Server spare kit FR1304S3HSBP
April 21, 2020	03	Adding Intel® Server Spares and Accessories
<a href="#">July 31, 2020</a>	<a href="#">04</a>	<a href="#">Removing Intel® Kit of Serial Port DB9 Adapter AXXRJ45DB93</a>



# Product Change Notification

## 117066 - 04

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2020. Other names and brands may be claimed as the property of others.

3D XPoint, ACEX, Altera, APEX, AnyWAN, Arria, Avalon, Axxia, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, CONVERGATE, Cyclone, Docea, eASIC, easicopy, Enpirion, Flexpipe, Hyperflex, Intel, the Intel logo, Intel Adaptix, Intel Agilex, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Falcon, Intel Inside, the Intel Inside logo, Intel Nervana, Intel Optane, Intel RealSense, Intel Shooting Star, Intel Sirius, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Iris, Itanium, MAX, Movidius, Myriad, neon, Nios, OpenVINO, the OpenVINO logo, Pentium, Puma, Quark, Quartus, SICOFI, Simics, SMARTi, SoftSilicon, Sound Mark, StarPro, Stratix, the Stratix logo, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcede, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS\* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.