



# Product Change Notification

## 107788 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 107788 - 00  
**Change Title:** SHW4URM2SA23, PCN 107788-00, Product Design, CLASS 2:Accessories,FHW4U2SASBP SAS backplane HSC firmware update  
**Date of Publication:** August 14, 2007

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Sep 7, 2007
---	-------------

## Description of Change to the Customer:

Update HSC Firmware on the SAS backplane to v2.06

SHW4URM2SA23

MM# 885102

Change top assembly part number from D61136-003 to D61136-004

Change the backplane part number from D55016-202 to D55016-203

FHW4U2SASBP

MM# 885051

Change top assembly part number from D64482-002 to D64482-003

Change the backplane part number from D55016-202 to D55016-203

## Customer Impact of Change and Recommended Action:

Customers may wish to perform testing and update their documentation

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
FHW4U2SASBP	885051	D64482-002	D55016-202	D42646-004	D55016-203
SHW4URM2SA23	885102	D61136-003	N/A	D61136-004	N/A

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

**Date of Revision:**  
August 14, 2007

**Revision Number:**  
00

**Reason:**  
Originally Published PCN