



Product Change Notification

109152 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109152 - 00
Change Title: Intel® Server Chassis SR2500, PCN 109152-00, Product Design, Adding Rivet Holes to SR2500 Tape Drive Bracket
Date of Publication: January 20, 2009

Key Characteristics of the Change:
Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 06, 2009
---	--------------

Description of Change to the Customer:

Rivet holes is being added to Intel® Server Chassis SR2500 tape drive bracket. This tape drive bracket will be reused on Intel next generation chassis which requires this design change.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
ASR2500CHSPR	880281	D43774-003	SR2500CHSPR	880281	D43774-004
ASR2500SATAPE	881260	D47440-002	ASR2500SATAPE	881260	D47440-003

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: January 20, 2009	Revision Number: 00	Reason: Originally Published PCN
--	-------------------------------	--