



Product Change Notification

112923 - 01

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2014. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	112923 - 01
Change Title:	Intel® Ethernet Switch FM4112 (EZFM4112F897L MM#930436), Intel® Ethernet Switch FM4212 (EZFM4212F1433C MM#930437, EZFM4212F1433E MM#930438), and Intel® Ethernet Switch FM4410 (FBFM4410F529C MM#920987, FBFM4410F529E MM#920988) PCN 112923-01 Product Discontinuance EOL Reason for Revision: Remove 2 SKUs from this EOL PCN: EZFM4112F897I and EZFM4224F1433I
Date of Publication:	July 23, 2014

Key Characteristics of the Change:
Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date:	Dec 31, 2014
Orders are Non-Cancelable and Non-Returnable After:	Dec 31, 2014
Last Product Discontinuance Shipment Date:	Mar 31, 2015

Description of Change to the Customer:

Reason for Revision: Remove 2 SKUs from this EOL PCN: EZFM4112F897I and EZFM4224F1433I

Due to lack of demand the products list in the table below for the Intel® Ethernet Switch FM4000 series will End of Life.

Customer Impact of Change and Recommended Action:

Customers should place their last time orders by Dec 31, 2014 and delivery of all orders must be taken no later than March 31, 2015.

Orders are non-cancelable and non-returnable after Dec 31, 2014.

Please contact your local Intel Field Sales representative if you have any further questions about this End of Life notice.

Products Affected / Intel Ordering Codes:

Marketing Name	Product Code	S-Spec	MM#	Stepping
Intel® Ethernet Switch FM4410	FBFM4410F529C	S LJM6	920987	A3
Intel® Ethernet Switch FM4410	FBFM4410F529E	S LJM7	920988	A3
Intel® Ethernet Switch FM4112	EZFM4112F897L	S LKAL	930436	A3
Intel® Ethernet Switch FM4212	EZFM4212F1433C	S LKAF	930437	A3
Intel® Ethernet Switch FM4212	EZFM4212F1433E	S LKAG	930438	A3

Products NOT Affected / Removed from Product Discontinuance:

Marketing Name	Product Code	S-Spec	MM#	Stepping
Intel® Ethernet Switch FM4224	EZFM4224F1433I	S LKAE	930429	A3
Intel® Ethernet Switch FM4112	EZFM4112F897I	S LKAK	930435	A3

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 12, 2014	00	Originally Published PCN
July 23, 2014	01	Remove 2 SKUs from this EOL PCN: EZFM4112F897 and EZFM4224F1433I