



Product Change Notification

111255 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asm.pcn@intel.com

Asia Pacific Contact: apacccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 111255 - 00
Change Title: Intel(R) Server Board S5520HC, S5520HCT, S5500HCV and Intel(R) Workstation Board S5520SC, PCN 111255-00, Product Design, Update BIOS, BMC and FRUSDR
Date of Publication: December 26, 2011

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jan 31, 2012
---	--------------

Description of Change to the Customer:

Intel will implement the following changes on Intel® Server Board S5520HC, S5500HCV and S5520HCT:

System Software programmed at the factory on the server board is being updated.

S5520HC, S5500HCV BIOS from production release 50 to production release 60;

S5520HCT BIOS from production release 50 to production release 60;

BMC from production release 53 to production release 58;

FRU/SDR from production release 28 to production release 30

The system software update, including Release notes for each, will be available for download from Intel's support website

http://www.intel.com/p/en_US/support/highlights/server/s5520hc prior to this change.

Please see software release notes for a list of changes when available.

Intel will also implement the following changes on Intel® Workstation Board S5520SC:

System Software programmed at the factory on the workstation board is being updated.

BIOS from production release 50 to production release 60;

BMC from production release 53 to production release 58;

FRU/SDR from production release 28 to production release 30

The system software update, including Release notes for each, will be available for download from Intel's support website

http://www.intel.com/p/en_US/support/highlights/server/s5520sc prior to this change.

Please see software release notes for a list of changes when available.

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact from these changes. Intel recommends that the customer perform a standard level of evaluation as updated product and software become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
S5520HCT	904912	E84149-556	E80888-556	S5520HCT	904912	E84149-557	E80888-557
BB5520HCR	905718	E87613-455	E26045-456	BB5520HCR	905718	E87613-456	E26045-457
BB5520SCR	905719	E87227-355	E30682-357	BB5520SCR	905719	E87227-356	E30682-358
BB5500HCVR	905720	E88252-455	E40912-457	BB5500HCVR	905720	E88252-456	E40912-458
S5520HCR	905721	E87228-456	E26045-456	S5520HCR	905721	E87228-457	E26045-457
S5520SCR	905722	E87503-356	E30682-357	S5520SCR	905722	E87503-357	E30682-358
S5500HCVR	905723	E87505-456	E40912-457	S5500HCVR	905723	E87505-457	E40912-458

PCN Revision History:

Date of Revision:
December 26, 2011

Revision Number:
00

Reason:
Originally Published PCN