



Product Change Notification

110121 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #:	110121 - 00
Change Title:	Intel PRO/100 S Dual Port Server Adapters (Gainesville Retail), PRO/100 S Desktop Adapters (MacKenzie Retail), and PRO/100 S Server Adapters (South Bend Retail & OEM generic) PCN 110121-00 Product Discontinuance End of Life
Date of Publication:	July 26, 2010

Key Characteristics of the Change:

Product Discontinuance

Forecasted Key Milestones:

Last Product Discontinuance Order Date:	Jul 30, 2011
Last Product Discontinuance Shipment Date:	Dec 31, 2011
Technical Support Service Ends:	Dec 31, 2012
Orders are Non-Cancelable and Non-Returnable After:	Oct 30, 2011

Description of Change to the Customer:

The Intel PRO/100 S Dual Port Server Adapters (Gainesville Retail), PRO/100 S Desktop Adapters (MacKenzie Retail), and PRO/100 S Server Adapters (South Bend Retail & OEM generic) will End of Life.

The Intel silicon controllers used on these Networking Adapters have announced End of Life on PCN#109390-00, dated July 24th, 2009, as follows; "Intel will be discontinuing the production of its legacy Fast Ethernet 10/100 PCI host-interface Silicon Components. This End of Life (EOL) plan is a LAN Access Division (LAD) business decision influenced by declining demand for all parts manufactured on an old process technology (P854) and the potential of increasing costs."

Customer Impact of Change and Recommended Action:

Customers should place their last time orders by July 30th, 2011, and delivery of all orders must be taken no later than December 31st, 2011. Orders are Non-Cancelable and Non-Returnable after October 30th, 2011, with Technical Support Service ending December 31, 2012.

Intel encourages all customers to upgrade to 10/100/1000 Mbps adapters. Recommended transition products are listed in the charts below.

	Brand Name	Product Code	MM#	Note
EOL Product	Intel® PRO/100 S Server Adapter South Bend	PILA8470C3 / PILA8470C3PAK5/ PILA8470D3G1P20	832702 832704 835046	10/100Mbps PCI-X Includes IPsec
Transition Product OR	Intel® PRO/1000 MT Server Adapter Everson	PWLA8490MT / PWLA8490MTBLK5/ PWLA8490MTG1P20	845956 847742 844795	10/100/1000Mbps PCI-X No IPsec
Transition Product	Intel® Gigabit ET Dual Port Server Adapter Portville DT	E1G42ET / E1G42ETBLK/ E1G42ETG1P20	897658 897654 897969	10/100/1000Mbps PCI Express Includes IPsec

	Brand Name	Product Code	MM#	Note
EOL Product	Intel® PRO/100 S Dual Port Server Adapter Gainesville	PILA8472C3 / PILA8472C3PAK5	829938 829939	10/100Mbps PCI-X Includes IP Sec
Transition Product OR	Intel® PRO/1000 MT Dual Port Server Adapter Double Barrow	PWLA8492MT / PWLA8492MTBLK5	844143 847743	10/100/1000Mbps PCI Express No IPsec
Transition Product	Intel® Gigabit ET Dual Port Server Adapter Portville DT	E1G42ET / E1G42ETBLK	897658 897654	10/100/1000Mbps PCI Express Includes IPsec

	Brand Name	Product Code	MM#	Note
EOL Product	Intel® PRO/100 S Desktop Adapter MacKenzie	PILA8460C3 / PILA8460C3BLK/ PILA8460C3J	832696 870508 838010	10/100Mbps PCI
Transition Product OR	Intel® PRO/1000 GT Desktop Adapter Stebbins 2 LF	PWLA8391GT / PWLA8391GTBLK / PWLA8391GTLBLK	864968 865080 865088	10/100/1000 Mbps PCI
Transition Product	Intel® Gigabit CT Desktop Adapter Shelter Island	EXPI9301CT / EXPI9301CTBLK	893646 893647	10/100/1000 Mbps PCI Express

Note on Discontinued Product Returns:

Approval from Intel, documented by an RMA# reference, must be obtained prior to the return of any product. No credit will be given for products returned by a distributor without prior authorization from Intel and unauthorized returns will be returned to the distributor, freight collect. Intel reserves the right to refuse credit if upon receipt of product it establishes that the terms of return, as defined in this policy, have not been met by distributor or if the product returned does not match the product described on the authorized RMA. Credit for returned products will be calculated based on the cost specified in the current Distributor Cost List in effect on the day that the return is authorized by Intel. Products included in the Discontinued Product Return Notification, as described in Product Discontinuance policy #188000, are not eligible for return under any other Intel® RMA program. No returns of any kind will be accepted for shrink-wrap software products if the shrink-wrap is broken.

As indicated below, certain types of RMA product must be returned in the original unopened, undamaged, and unadjusted packaging. Where this requirement is not met, Intel reserves the right to return the product to distributor, freight collect, or to charge distributor a 20% administration fee when calculating credit for return. It is the responsibility of the distributor to ensure that RMA product is adequately protected to reasonably ensure that damage in-transit to Intel does not occur.

Products Affected / Intel Ordering Codes:

Product Name	Product Code	Pre Change Affected MM#
Intel PRO/100 S Dual Port Server Adapter (Gainesville Retail single)	PILA8472C3	829938
Intel PRO/100 S Dual Port Server Adapter (Gainesville Retail 5-pak)	PILA8472C3PAK5	829939
Intel PRO/100 S Desktop Adapter (MacKenzie Retail single)	PILA8460C3	832696
Intel PRO/100 S Desktop Adapter (MacKenzie Retail 20-pak)	PILA8460C3BLK	870508
Intel PRO/100 S Desktop Adapter (MacKenzie Retail Japan)	PILA8460C3J	838010
PRO/100 S Server Adapter (South Bend Retail single)	PILA8470C3	832702
PRO/100 S Server Adapter (South Bend Retail 5-pak)	PILA8470C3PAK5	832704
PRO/100 S Server Adapter (South Bend OEM generic)	PILA8470D3G1P20	835046

Reference Documents / Attachments:

Document:	Location #:

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
July 26, 2010	00	Originally Published PCN