



Product Change Notification

110766 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110766 - 00
Change Title: Intel® Server System P4304BTLSEFCN, P4304BTLSEHCN, R1304BTLSEFAN, R1304BTLSEHBN, and R1304BTLSESSFAN, PCN 110766 - 00, Product Material, Label, Korea Regulatory Label Change
Date of Publication: June 22, 2011

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Jun 30, 2011
---	--------------

Description of Change to the Customer:

Intel is implementing the following changes on the Intel® Server System R1304BTLSEFAN, R1304BTLSEHBN, R1304BTLSESSFAN, P4304BTLSEFCN and P4304BTLSEHCN.

- 1) Updating the box labels on the outer product packaging to add the new Korea Certification (KC) mark. The following is a picture of the new KC mark:



- 2) Updating the Serial Number label on the chassis to add the manufacturing date (MMYY). The following is the example of the picture of the old Serial Number label:



The following is the example of the picture for the new Serial Number label:



This KC mark change is for the new Korea Regulatory Marking requirements on both the product and packaging box:

1. New KC mark with unique certification number
2. Human readable date information (month and year)
3. Manufacturers Name
4. Equipment Name
5. Country of Origin

Customer Impact of Change and Recommended Action:

Customers may need to determine the need for changing of the KC marking on their products before they are exported to or sold in the Republic of Korea market.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change Product Code	Pre Change MM#	Pre Change TA
R1304BTLSHBN	911688	G19777-002	R1304BTLSHBN	911688	G19777-002
R1304BTLSFAN	911698	G19672-002	R1304BTLSFAN	911698	G19672-002
R1304BTSSFAN	911709	G22737-002	R1304BTSSFAN	911709	G22737-002
R1304BTLSHBNNA	907658	G19777-002	R1304BTLSHBNNA	907658	G19777-002
R1304BTLSFANNA	907775	G19672-002	R1304BTLSFANNA	907775	G19672-002
R1304BTSSFANNA	907569	G22737-002	R1304BTSSFANNA	907569	G22737-002
P4304BTLSHCNNA	907886	G22759-001	P4304BTLSHCNNA	907886	G22759-001
P4304BTLSFCNNA	908252	G22757-001	P4304BTLSFCNNA	908252	G22757-001
P4304BTLSHCN	912775	G22759-001	P4304BTLSHCN	912775	G22759-001
P4304BTLSFCN	912776	G22757-001	P4304BTLSFCN	912776	G22757-001

PCN Revision History:

Date of Revision:

June 22, 2011

Revision Number:

00

Reason:

Originally Published PCN