



Product Change Notification

109429 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109429 - 00
Change Title: Intel® Server Systems SR2600UR,
SR2625UR Power Supply Spare, PCN
109429-00, Product Design, Firmware update
to address errata
Date of Publication: July 22, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Aug 14, 2009 |
|---|--------------|

Description of Change to the Customer:

The firmware on the AXX750WPS power supply is being updated to address errata #25. Please see the SR5520UR Monthly Specification Update posted on Intel's support website for more information.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers.

Products Affected / Intel Ordering Codes:

| Pre Change Product Code | Pre Change MM# | Pre Change TA | Pre Change PBA | Post Change TA | Post Change PBA |
|-------------------------|----------------|---------------|----------------|----------------|-----------------|
| AXX750WPS | 901681 | E58998-001 | E30692-006 | E58998-002 | E30692-007 |

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

| | | |
|---|-------------------------------|--|
| Date of Revision: July 22, 2009 | Revision Number: 00 | Reason: Originally Published PCN |
|---|-------------------------------|--|