



Product Change Notification

108794 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108794 - 00
Change Title: Intel® Embedded Processors, PCN 108794-00, Product Marking, Country of Origin (COO) Mark Changing from Philippines to Malaysia
Date of Publication: September 12, 2008

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 13, 2008
---	--------------

Description of Change to the Customer:

In order to ensure a continuous supply of the Intel® Embedded Processors listed in the Products Affected Table below, these products will be transferring to another Intel qualified assembly site. The new site is located in Malaysia. Traceability will be maintained through the Country of Origin (COO) identification code marked on the product. Products will be transferring from an Intel assembly site located in the Philippines. All material and equipment will remain the same.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers for this change. Customers may see products from either assembly site until current inventory is depleted. Customers may want to notify their receiving department of the change in Country of Origin marking.

Products Affected / Intel Ordering Codes:

Affected Product Code	Affected S-Spec	Affected MM#
RK80530RY009256	S L6C8	847856
RK80530KZ012512	S L6BX	847861
RK80530KZ017512	S L6BY	847862
RH80535GC0251M	S L6FA	848226
RH80535NC013512	S L6N7	851232
NK80530KZ933512	S L7T3	863671
NK80530KZ800512	S L7T4	863863
NK80530MZ733256	S L7UH	863864
NK80530VY650256	S L7UJ	863865
NK80530VY400256	S L7UK	863867
RH80536GE0412M	S L7SM	864656
NK80530MZ866256	S L7XH	865221
NK80530VZ733256	S L7YA	865573
NK80530VZ800256	S L7YB	865574
NPIXP2400BB		865905
NPIXP2400BBT		865908
LE80536GE0412M	S L869	867109
LE80536LC0172M	S L89N	868295
LE80535GC0251M	S L8BH	869601
LE80535LC0051M	S L8FL	870139
LE80535NC013512	S L8FM	870148
LE80535VC600512	S L8FN	870152
LE80536VC001512	S L8LW	871728
LE80536NC0211M	S L8MT	872115
LE80535VC6000	S L8LE	872310
NE80546RE051256	S L8HH	872491
NE80546RE072256	S L8HM	872500
NE80546PG0801M	S L8JZ	872636
RH80536GC0332M	S L8U6	875183
LE80536GC0332M	S L8U8	875186
LE80554VC0010M	S L8XR	876239
LE80554VC9000M	S L8XS	876240
LE80554VC8000M	S L8XT	876241
LF80539GF0412MX	S L9EH	881984
LE80539UE0092MX	S L9JQ	882751
LE80539LF0282MX	S L9JT	882790
LE80539GF0412MX	S L9K2	882800
LF80539KF0412M	S L9HN	883108
LF80539KF0282M	S L9HP	883109
LF80539JF0282M	S L9HS	883111
LF80538NE0361ME	S L9KW	883490
LE80538VE0041ME	S L9L7	883549
LE80538VE0091ME	S L9L8	883551
LE80538UE0092MX	S L9LB	883592
LE80538UE0142MX	S L9LC	883777
LE80538NE0361ME	S L9LF	884036
LF80538KF0341M	S L9S2	884317
LF80538KF0281M	S L9S3	884318

LE80539UE0042M	S L9UR	885507
NPIXP2855AD	S LA83	890001
NPIXP2805AD	S LA85	890006
NPIXP2855AC	S LA87	890008
NPIXP2805AC	S LA89	890010
LE80536VC900512	S LAFK	891299

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
September 12, 2008	00	Originally Published PCN