



Product Change Notification

110844 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asm.pcn@intel.com

Asia Pacific Contact: apacccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110844 - 00
Change Title: Intel(R) Server Board S1200BTL, PCN 110844-00, Product Material, Product Material, Update Software Stack; Change CPU protective cover
Date of Publication: July 17, 2011

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Aug 01, 2011
---	--------------

Description of Change to the Customer:

Intel is updating below changes on the Intel(R) Server Board S1200BTL:

- 1) Updating the CPU protective cover to reduce the possibility of pin damage. Below is a picture of the new protective plate:



- 2) Updating the software package to BIOS revision 28, BMC revision 1.07, and FRUSDR revision 1.07. The software package including Release notes for each will be available for download from Intel's support site http://downloadcenter.intel.com/Detail_Desc.aspx?agr=Y&DwnldID=20196&lang=eng&OSVersion=OS%20Independent&DownloadType=Firmware prior to this change. Please see software release notes for a list of changes.

Customer Impact of Change and Recommended Action:

The change of the CPU protective cover has no functional impact but may require process change when assembling a CPU. Intel recommends that the customer perform a standard level of evaluation as the updated product and software become available.

Products Affected / Intel Ordering Codes:

Pre Change	Pre	Pre Change	Pre	Post Change	Post Change
------------	-----	------------	-----	-------------	-------------

Product Code	Change MM#	TA	Change PBA	TA	PBA
S1200BTL	911776	G23533-307	E98681-307	G23533-308	E98681-308
BBS1200BTL	911645	G23533-307	E98681-307	G23533-308	E98681-308
DBS1200BTL	911797	G23533-307	E98681-307	G23533-308	E98681-308

PCN Revision History:

Date of Revision:

July 17, 2011

Revision Number:

00

Reason:

Originally Published PCN