



# Product Change Notification

**Change Notification #:** 117195 - 01

**Change Title:** Intel® NUC Kit, NUC7i3BNK,  
Intel® NUC Kit, NUC7i3BNH,  
Intel® NUC Kit w/ 16GB Intel® Optane™  
memory,  
Intel® NUC Board NUC7i3BNB,  
Intel® NUC Kit, NUC7i5BNK,  
Intel® NUC Kit, NUC7i5BNH,  
Intel® NUC Board NUC7i5BNB,  
Intel® NUC Kit, NUC7i7BNH,  
Intel® NUC Board NUC7i7BNB,  
Intel® NUC 7 Home, a mini PC with  
Windows® 10, Intel® Core™ i3, 1TB,  
16GB Intel® Optane™ Memory,  
4GB DDR4,  
Intel® NUC 7 Home, a mini PC with  
Windows® 10, Intel® Core™ i5, 1TB,  
16GB Intel® Optane™ Memory,  
4GB DDR4,  
Intel® NUC 7 Enthusiast, a mini PC with  
Windows® 10, Intel® Core™ i7, 2TB,  
32GB Intel® Optane™ Memory, 8GB,  
Intel® NUC 7 Home, a mini PC with  
Windows® 10, Intel® Core™ i5, 256GB  
NVMe SSD, 8GB RAM,  
Intel® NUC 7 Enthusiast, a mini PC with  
Windows® 10, Intel® Core™ i7, 512GB  
NVMe SSD, 16GB RAM,  
PCN 117195-01, Product Design,  
BIOS update and Windows image update,  
[Reason for Revision: Correction of BIOS  
version.](#)

**Date of Publication:**                    **October 24, 2019**

**Key Characteristics of the Change:**

Product Design

**Forecasted Key Milestones:**

|   |                  |
|---|------------------|
| <b>Date Customer Must be Ready to Receive Post-Conversion Material:</b> | November 1, 2019 |
|---|------------------|

**Description of Change to the Customer:**

**Reason for Revision: Correction of BIOS version.**

The Intel® NUC SKUs listed in the Product Affected Table below will have the following change.

1. Update BIOS from [BN078](#) to BN0080
2. Update BN L10 SKUs image from Windows 10 Redstone 5 to Windows 19H1.

**Customer Impact of Change and Recommended Action:**

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel validation of a new board revision does not include testing with older versions of BIOS.

The Windows Image Update should have no impact for customers.

Milestone dates are estimates and subject to change based on business and operational conditions.

Customer can expect to receive mixed inventory until current inventory levels are depleted.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

## Products Affected / Intel Ordering Codes:

| Product Code    | MM#    | Pre Change SA | Pre Change AA | Post Change SA | Post Change AA |
|-----------------|--------|---------------|---------------|----------------|----------------|
| BOXNUC7I7BNH    | 950951 | J31153-313    | J31145-312    | J31153-314     | J31145-313     |
| BOXNUC7I7BNHL   | 950952 | J57677-312    | J31145-312    | J57677-313     | J31145-313     |
| BOXNUC7I5BNK    | 950955 | J31159-313    | J31144-312    | J31159-314     | J31144-313     |
| BOXNUC7I5BNKL   | 950957 | J57665-312    | J31144-312    | J57665-313     | J31144-313     |
| BOXNUC7I5BNH    | 950959 | J31169-313    | J31144-312    | J31169-314     | J31144-313     |
| BOXNUC7I5BNHL   | 950961 | J57645-312    | J31144-312    | J57645-313     | J31144-313     |
| BOXNUC7I3BNK    | 950963 | J31188-315    | J22859-315    | J31188-316     | J22859-316     |
| BOXNUC7I3BNKL   | 950965 | J50876-315    | J22859-315    | J50876-316     | J22859-316     |
| BOXNUC7I3BNH    | 950967 | J31191-315    | J22859-315    | J31191-316     | J22859-316     |
| BOXNUC7I3BNHL   | 950969 | J50874-315    | J22859-315    | J50874-316     | J22859-316     |
| BLKNUC7I3BNB    | 955782 | N/A           | J22859-315    | N/A            | J22859-316     |
| BLKNUC7I5BNB    | 955784 | N/A           | J31144-312    | N/A            | J31144-313     |
| BLKNUC7I7BNB    | 955785 | N/A           | J31145-312    | N/A            | J31145-313     |
| BOXNUC7I3BNHX1  | 958546 | J59435-109    | J22859-315    | J59435-110     | J22859-316     |
| BOXNUC7I5BNHX1  | 958547 | J59438-109    | J31144-312    | J59438-110     | J31144-313     |
| BOXNUC7I7BNHX1  | 958548 | J59452-109    | J31145-312    | J59452-110     | J31145-313     |
| BOXNUC7I3BNHX1L | 958755 | J61817-311    | J22859-315    | J61817-312     | J22859-316     |
| BOXNUC7I5BNHX1L | 958756 | J61813-311    | J31144-312    | J61813-312     | J31144-313     |
| BOXNUC7I7BNHX1L | 958757 | J61751-311    | J31145-312    | J61751-312     | J31145-313     |
| BOXNUC7I7BNHXG  | 960827 | J69975-112    | J31145-312    | J69975-113     | J31145-313     |
| BOXNUC7I7BNHXGL | 960839 | J69977-110    | J31145-312    | J69977-111     | J31145-313     |
| BOXNUC7I5BNHXF  | 960845 | J69978-112    | J31144-312    | J69978-113     | J31144-313     |
| BOXNUC7I5BNHXFL | 960846 | J69980-110    | J31144-312    | J69980-111     | J31144-313     |
| BOXNUC7I3BNHXF  | 960847 | J69982-111    | J22859-315    | J69982-112     | J22859-316     |
| BOXNUC7I3BNHXFL | 960848 | J69985-109    | J22859-315    | J69985-110     | J22859-316     |
| BOXNUC7I5BNKPL  | 962995 | J79521-110    | J31144-312    | J79521-111     | J31144-313     |
| BOXNUC7I5BNKPL  | 963000 | J79544-108    | J31144-312    | J79544-109     | J31144-313     |
| BOXNUC7I7BNKQ   | 963162 | J79498-110    | J31145-312    | J79498-111     | J31145-313     |
| BOXNUC7I7BNKQL  | 963164 | J79519-108    | J31145-312    | J79519-109     | J31145-313     |

## PCN Revision History:

| Date of Revision:                | Revision Number:   | Reason:                                     |
|----------------------------------|--------------------|---|
| October 9, 2019                  | 00                 | Originally Published PCN                    |
| <a href="#">October 24, 2019</a> | <a href="#">01</a> | <a href="#">Correction of BIOS version.</a> |



# Product Change Notification

## 117195 - 01

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

**Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.**

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apagccb@intel.com](mailto:apagccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2019. Other names and brands may be claimed as the property of others.

3D XPoint, Axxia, Basis, Basis Peak, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, Curie, Flexpipe, Intel, the Intel logo, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Inside, the Intel Inside logo, Intel Insider, Intel Joule, Intel RealSense, Intel SingleDriver, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Iris, Itanium, MCS, MMX, Optane, Ostro, Pali, Pentium, picoArray, Picochip, picoXcell, Puma, Quark, SMARTi, Soletta, Sound Mark, StarPro, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcede, True Key, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS\* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.