



Product Change Notification

Change Notification #: 116374 - 00

Change Title: Intel® JHL7340 Thunderbolt™ 3 Controller, Intel® JHL7340 Thunderbolt™ 3 Controller, Intel® JHL7440 Thunderbolt™ 3 Controller, Intel® JHL7440 Thunderbolt™ 3 Controller, Intel® JHL7540 Thunderbolt™ 3 Controller, and Intel® JHL7540 Thunderbolt™ 3 Controller, PCN 116374-00, Product Marking, Product Marking Contrast Update

Date of Publication: July 26, 2018

Key Characteristics of the Change:

Product Marking


Forecasted Key Milestones:

| | |
|---|-----------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | August 26, 2019 |
|---|-----------------|

Description of Change to the Customer:

The product markings on the Intel® JHL7340 Thunderbolt™ 3 Controller, Intel® JHL7440 Thunderbolt™ 3 Controller, and Intel® JHL7540 Thunderbolt™ 3 Controller products listed in the Products Affected table, will have the laser mark modified to improve contrast and readability. There is no change to form, fit, or function.

Example below showing contrast improvements:



Customer Impact of Change and Recommended Action:

Milestone dates are estimates and subject to change based on business and operational conditions. Customers can expect to receive mixed inventory with the pre and post marking until current inventory levels have been depleted.

Customers should take note of this change and notify their receiving, quality or incoming inspection groups, and subcontractors of this change, to avoid confusion or delays in receiving.

Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

| Marketing Name | Product Code | S-Spec | MM# |
|--|--------------|--------|--------|
| Intel® JHL7340 Thunderbolt™ 3 Controller | JHL7340 | S LMHX | 964383 |
| Intel® JHL7340 Thunderbolt™ 3 Controller | JHL7340 | S LMHY | 964393 |
| Intel® JHL7440 Thunderbolt™ 3 Controller | JHL7440 | S LMHZ | 964458 |
| Intel® JHL7440 Thunderbolt™ 3 Controller | JHL7440 | S LMJ2 | 964470 |
| Intel® JHL7540 Thunderbolt™ 3 Controller | JHL7540 | S LMHR | 964275 |
| Intel® JHL7540 Thunderbolt™ 3 Controller | JHL7540 | S LMHS | 964276 |

PCN Revision History:

Date of Revision:

July 26, 2018

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

116374 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2018. Other names and brands may be claimed as the property of others.

3D XPoint, Axxia, Basis, Basis Peak, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, Curie, Flexpipe, Intel, the Intel logo, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Inside, the Intel Inside logo, Intel Insider, Intel Joule, Intel RealSense, Intel SingleDriver, Intel SpeedStep, Intel Unite, Intel vPro, Intel Xeon Phi, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Iris, Itanium, MCS, MMX, Optane, Ostro, Pali, Pentium, picoArray, Picochip, picoXcell, Puma, Quark, SMARTi, Soletta, Sound Mark, StarPro, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcende, True Key, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos. Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.