



Product Change Notification

109597 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109597 - 00
Change Title: Intel® Modular Server System MFSYS25, Intel® Modular Server System MFSYS35, Intel® Management Module MFCMM, Intel® Storage Controller AXXSCM3S, MF MIDPLANE Midplane Spare, MFHDDBAY25 2.5" HDD Bay Module Spare, MFHDDBAY35 3.5" HDD Bay Module Spare, PCN 109597-00, Product Material, Updating System Components and Spares to Firmware Version 4.1. Also Updating Flash Memory on the MFCMM.
Date of Publication: September 24, 2009

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Oct 23, 2009
---	--------------

Description of Change to the Customer:

Updating the firmware installed on the system components and spares in the factory to V4.1. Update supports upgrade to 2G SD card on the system midplane and brings all platform components to a common firmware level. Reference PCN109490-0x for information on the 2G SD card upgrade. Also, updating to a new flash memory part on the MFCMM to replace an EOL part.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers and recommends no additional action.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change Product Code	Post Change MM#	Post Change TA	Post Change PBA
AXXSCM3S 891831	891831	E15895-004	D70737-408	AXXSCM3S 891831	891831	E15895-005	D70737-409
MFCMM 891834	891834	E16293-004	D70735-405	MFCMM 891834	891834	E16293-005	D70735-406
MF MIDPLANE 899916	899916	E19078-003	D70484-407	MF MIDPLANE 899916	899916	E19078-004	D70484-408
MFSYS25 902318	902318	D91400-008		MFSYS25 902318	902318	D91400-009	
MFSYS35 902319	902319	D91403-005		MFSYS35 902319	902319	D91403-006	
MFHddbAY25 892137	892137	E19048-003	D70481-405	MFHddbAY25 892137	892137	E19048-004	D70481-406
MFHddbAY35 892139	892139	E32648-004	D91372-303	MFHddbAY35 892139	892139	E32648-005	D91372-304

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 24, 2009

Revision Number:

00

Reason:

Originally Published PCN