



Product Change Notification

108756 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jcb.ijkk@intel.com

Copyright © Intel Corporation 2008. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 108756 - 00
Change Title: DG35EC, PCN 108756-00, Product Design, BIOS Update
Date of Publication: August 28, 2008

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 18, 2008
---	--------------

Description of Change to the Customer:

Update BIOS to ECG3510M.86A.0106 and update to 1394/LAN EEPROM file. Please refer to the release notes posted at <http://developer.intel.com/products/motherboard/DG35EC/tools.htm>

Customer Impact of Change and Recommended Action:

These changes have been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. It is recommended that customers evaluate this new BIOS to ensure a smooth transition.

Intel is not recommending additional qualification of these changes on platforms received from Intel. This change is not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXDG35EC	896207	E29266-205	E29266-206
BLKDG35EC	896208	E29266-205	E29266-206
LADG35EC	897336	E37012-205	E37012-206
BOXDG35ECC	898194	E39017-205	E39017-206
BLKDG35ECC	898195	E39017-205	E39017-206

PCN Revision History:

Date of Revision: August 28, 2008	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--