



# Product Change Notification

## 109782 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109782 - 00  
**Change Title:** Intel® Server Accessory FXX25HDDCAR, PCN 109782-00, Product Design, 2.5 HDD Carrier Design is changed  
**Date of Publication:** January 18, 2010

## Key Characteristics of the Change:

Product Design


## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Feb 05, 2010
---	--------------

## Description of Change to the Customer:

The 2.5 Inch HDD Carrier is changed to remove the Gusset plate from both the left rail and right rail. Please refer to the following photos to know the detail. The modification is to allow more hard disk models on Intel® Modular Server MFSYS25 which bundle this kind of hard disk carriers. This change does not impact any other Intel® chassis.

Pre Change Carrier:



Post Change Carrier:



**Customer Impact of Change and Recommended Action:**

Intel encourages customers to review this change and determine the impact related to their specific application and usage.

**Products Affected / Intel Ordering Codes:**

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change Product Code	Post Change MM#	Post Change TA
FXX25HDDCAR	881681	D39993-001	FXX25HDDCAR	881681	D39993-002

**Reference Documents / Attachments:**

Document: \_\_\_\_\_ Location #: \_\_\_\_\_

**PCN Revision History:**

<b>Date of Revision:</b>	<b>Revision Number:</b>	<b>Reason:</b>
January 18, 2010	00	Originally Published PCN