## intel.

# **Product Change Notification**

Change Notification #: 118193 - 00

Change Title: Intel® Stratix® 10 H-Tile/L-Tile Devices,

PCN 118193-00, Software,

**PCIe Update** 

Date of Publication: April 7, 2021

#### **Key Characteristics of the Change:**

Software

#### **Forecasted Key Milestones:**

Milestone	Availability
Availability of PCIe Express* update to the Intel® Stratix® 10 H-Tile/L-Tile devices	Now

#### **Description of Change to the Customer:**

This is the same change described in ADV2105 issued on March 31, 2021.

Intel is notifying customers of an important PCIe Express\* update to the Intel® Stratix® 10 H-Tile/L-Tile devices. Refer to Table 1 for details and link to KDB article with recommendations and further actions.

#### Table 1

	Update Details	Impacted software versions	KDB Article
•	When using the Intel® L-tile and H-tile Avalon® Streaming	All Intel Quartus	Why does the Intel® L-tile
	and Avalon® Memory Mapped IP for PCI Express* in Gen3	Prime Pro Edition	and H-tile Avalon®
	Root Port mode, correctable errors or link down training may	software ver20.2	Streaming and Avalon®
	be observed due to sub-optimal preset bit settings for PCIe*	and prior	Memory Mapped IP for PCI
	Upstream Port (USP)/Downstream Port (DSP) Gen3 Root Port		Express* observe
	IP on both H tile and L tile.		correctable errors/link down
•	Permanent fix implemented in Intel® Quartus® Prime Pro		train when operating in
	Edition software ver20.3 and above.		Gen3 Root Port mode?

Page 1 of 3 PCN #118193 - 00

#### **Customer Impact of Change and Recommended Action:**

For more information, please contact your local Sales representative, or submit a question or request at the My Intel support page, log-in via: <a href="https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html">https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html</a>

#### **Products Affected / Intel Ordering Codes:**

Impacted device families are Intel Stratix 10 H-Tile/L-Tile GX, MX, NX, SX, TX devices.

The list of affected part numbers (OPNs) can be downloaded in Excel form:

https://www.intel.com/content/dam/www/programmable/us/en/pdfs/literature/pcn/adv2105-opn-list.xlsx

**PCN Revision History:** 

Date of Revision: Revision Number: Reason:

April 7, 2021 00 Originally Published PCN

Page 2 of 3 PCN #118193 - 00

### intel.

# Product Change Notification 118193 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com
Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: <a href="mailto:eccb@intel.com">eccb@intel.com</a>
Japan Email: <a href="mailto:jccb.ijkk@intel.com">jccb.ijkk@intel.com</a>

Copyright © Intel Corporation 2021. Other names and brands may be claimed as the property of others.

3D XPoint, ACEX, Altera, APEX, AnyWAN, Arria, Avalon, Axxia, BlueMoon, BunnyPeople, Celeron, Centrino, Cilk, CONVERGATE, Cyclone, Docea, eASIC, easicopy, Enpirion, Flexpipe, Hyperflex, Intel, the Intel logo, Intel Adaptix, Intel Agilex, Intel Atom, Intel CoFluent, Intel Core, Intel. Experience What's Inside, the Intel. Experience What's Inside logo, Intel Falcon, Intel Inside, the Intel Inside logo, Intel Nervana, Intel Optane, Intel RealSense, Intel Shooting Star, Intel Sirius, Intel SpeedStep, Intel Unite, Intel VPro, Intel Xeon Phi, Iris, Itanium, MAX, Movidius, Myriad, neon, Nios, OpenVINO, the OpenVINO logo, Pentium, Puma, Quarkus, SICOFI, Simics, SMARTi, SoftSilicon, Sound Mark, StarPro, Stratix, the Stratix logo, Stay With It, the Engineering Stay With It logo, StreamSight, Tarari, The Journey Inside, Thunderbolt, the Thunderbolt logo, Transcede, Ultrabook, VTune, Xeon, X-GOLD, XMM, X-PMU and XPOSYS are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries.

Microsoft, Windows, and the Windows logo are trademarks, or registered trademarks of Microsoft Corporation in the United States and/or other countries. Java is a registered trademark of Oracle and/or its affiliates. Bluetooth is a trademark owned by its proprietor and used by Intel Corporation under license. Intel Corporation uses the Palm OS\* Ready mark under license from Palm, Inc. OpenCL and the OpenCL logo are trademarks of Apple Inc. used by permission by Khronos.

Learn how to use Intel Trademarks and Brands correctly at <a href="http://www.intel.com/intel/legal/tmusage2.htm">http://www.intel.com/intel/legal/tmusage2.htm</a>.

Page 3 of 3 PCN #118193 - 00