



Product Change Notification

109566 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: <mailto:asmo.pcn@intel.com>

Asia Pacific Contact: <mailto:apacgccb@intel.com>

Europe Email: <mailto:eccb@intel.com>

Japan Email: <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109566 - 00
Change Title: D945GCLF, D945GCLF2, and D945LF2D, PCN 109566-00, Product Design, EUP compliance and BIOS update
Date of Publication: September 02, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Sep 24, 2009
---	--------------

Description of Change to the Customer:

Intel has implemented the following changes:

- Wake from serial capability is being removed to meet EUP requirements.
- The BIOS is being updated from 0182 to 0229.

To access release notes or a copy of the BIOS for evaluation, please go to <http://downloadcenter.intel.com>

Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality or reliability implications to our customers. Intel is not recommending additional qualification of these changes on desktop boards received from Intel.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BLKD945GCLF	896267	E27042-406	E27042-407
BOXD945GCLF	896268	E27042-406	E27042-407
LAD945GCLF	896269	E27044-406	E27044-407
LAD945GCLFS2	899630	E46423-405	E46423-406
LAD945GCLFW5	902149	E62503-403	E62503-404
BOXD945GCLF2	896272	E46416-107	E46416-108
BLKD945GCLF2	896273	E46418-107	E46418-108
LAD945GCLF2	896275	E46417-110	E46417-111
BOXD945GCLF2D	901738	E59323-104	E46416-105
LAD945GCLF2D	901740	E59321-104	E59321-105
BLKD945GCLF2D	901768	E59324-104	E59324-105

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

September 2, 2009

Revision Number:

00

Reason:

Originally Published PCN