



Product Change Notification

109887 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109887 - 00
Change Title: Intel(R) Server Board S5000VSA, PCN 109887-00, Product Design, Update Resource CD, Intel(R) System Management Software DVD and Attention Document
Date of Publication: March 17, 2010

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 23, 2010
---	--------------

Description of Change to the Customer:

Intel will implement the following changes on Intel® Server Board S5000VSA:

1. Updating the resource CD to include new drivers, documentation and software license document;
2. Updating Intel® System Management Software DVD to version 3.6.1;
3. Removing old attention document E58651-001; Updating attention document from D36974-005 to D36974-006 for boxed board and adding attention document E87713-001 for OEM pack to include software license document.

For customers who would like to evaluate, the new drivers can be obtained from below Intel support website when available
<http://www.intel.com/support/motherboards/server/S5000VSA/>

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact from these changes. Intel recommends that the customer perform a standard level of evaluation as updated product and software become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
S5000VSA4DIMMR	901741	E10009-006	901741	E10009-007
BSA2BBR	901742	E10042-007	901742	E10042-008
BSA2VBBR	901743	E10049-006	901743	E10049-007
S5000VSASCSIR	901744	E10041-007	901744	E10041-008
S5000VSASATAR	901745	E10040-007	901745	E10040-008
S5000VSASASR	901746	E10035-006	901746	E10035-007

BSA2SASBBR	901747	E10047-006	901747	E10047-007
S5000VSA4DIMMR	901741	E10009-006	901741	E10009-007

Reference Documents / Attachments:

Document: **Location #:**

PCN Revision History:

Date of Revision:	Revision Number:	Reason:
March 17, 2010	00	Originally Published PCN