



# Product Change Notification

## 109477 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific Contact:** [apagccb@intel.com](mailto:apagccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109477 - 00  
**Change Title:** Intel(R) Server Board S5000VSA, PCN 109477-00, Product Material, BIOS Update  
**Date of Publication:** July 08, 2009

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Aug 10, 2009
---	--------------

## Description of Change to the Customer:

Intel is updating S5000VSA server board BIOS from version R0096 to version R0098 - see BIOS release notes for details.

## Customer Impact of Change and Recommended Action:

Intel recommends customers evaluate BIOS R0098 when available in July 2009. Independent of this BIOS update implemented at Intel factory on the S5000VSA, the latest software package, including the BIOS update R0098, can be obtained at the link below.  
<http://support.intel.com/support/motherboards/server/s5000vsa/index.htm>

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S5000VSA4DIMMR	901741	E10009-005	E11011-201	901741	E10009-006	E11011-202
BSA2BBR	901742	E10042-006	E11003-201	901742	E10042-007	E11003-202
BSA2VBBR	901743	E10049-005	E11011-201	901743	E10049-006	E11011-202
S5000VSASCSIR	901744	E10041-006	E11003-201	901744	E10041-007	E11003-202
S5000VSASATAR	901745	E10040-006	E11003-201	901745	E10040-007	E11003-202
S5000VSASASR	901746	E10035-005	E11012-201	901746	E10035-006	E11012-202
BSA2SASBBR	901747	E10047-005	E11012-201	901747	E10047-006	E11012-202

## Reference Documents / Attachments:

**Document:** **Location #:**

## PCN Revision History:

<b>Date of Revision:</b> July 8, 2009	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
--	-------------------------------	--