



# Product Change Notification

## 110749 - 00

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2011. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 110749 - 00  
**Change Title:** Intel® Server Board S3240GPLX,  
S3420GPLC, S3420GPV, Intel® Server  
System SR1630GP, SR1630HGP, PCN  
110749-00, Label, Korea Communications  
Commission (KCC) mark change  
**Date of Publication:** June 09, 2011

## Key Characteristics of the Change:

Label

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jul 08, 2011
---	--------------

## Description of Change to the Customer:

Intel will implement the following changes on the Intel® Server Board S3420GPLC, S3420GPLX, S3420GPV and Intel® Server System SR1630GP, SR1630HGP.

1) Updating the Regulatory Label on the packaging box to remove the old Korea Communications Commission (KCC) mark. The following is a picture of the old Regulatory Label.



The following is a picture of the new Regulatory Label.



この装置は、クラス A 情報技術装置です。この装置を家庭環境で使用すると電波妨害を引き起こすことがあります。この場合には使用者が適切な対策を講ずるよう要求されることがあります。VCCI-A

This device complies with Part 15 of the FCC Rules. Operation of this device is subject to the following two conditions:  
 (1) This device may not cause harmful interference, and  
 (2) This device must accept any interference received, including interference that may cause undesired operation.

CANADA ICES-003 CLASS A

D52938-006



2) Updating the box labels on the outer product packaging to add the new Korea Certification (KC) mark. The following is a picture of the new KC mark.



3) Updating the Safety label on the chassis to replace the old KCC mark with the new KC mark. The following is a picture of the old safety Label.



The following is a picture of the new safety label.




4) Updating the Serial Number label on the chassis to add the manufacturing date (MMM YY). The following is a picture of the old Serial Number label.



The following is a picture of the new Serial Number label.



5) Adding a label with the new KC mark and the manufacturing date (MMM YY) on the system board. The following is a picture of the label.



This KC mark change is for the new Korea Regulatory Marking requirements on both the product and the packaging box.

1. New KC mark with unique certification number
2. Human readable date information (month and year)
3. Manufacturers Name
4. Equipment Name
5. Country of Origin

## Customer Impact of Change and Recommended Action:

Customers may need to determine the need for changing of the KC marking on their products before they are exported to or sold in the Republic of Korea market.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
S3420GPV	902726	E84395-109	E80883-107	E84395-110	E80883-108
S3420GPLC	907524	E74801-408	E51976-406	E74801-409	E51976-407
S3420GPLX	907525	E74800-408	E51974-406	E74800-409	E51974-407
SR1630GP	907506	E65196-009	E51976-406	E65196-010	E51976-407
SR1630HGP	907517	E65540-009	E51976-406	E65540-010	E51976-407
SR1630GPNA	905769	E65196-009	E51976-406	E65196-010	E51976-407
SR1630HGPNA	905819	E65540-009	E51976-406	E65540-010	E51976-407
BB3420GPV	902728	E89003-107	E77063-304	E89003-108	E77063-305
BB3420GPLC	907526	E77963-406	E51976-406	E77963-407	E51976-407
BB3420GPLXSASM	909787	G14597-002	E51974-406	G14597-003	E51974-407

## PCN Revision History:

**Date of Revision:**

June 7, 2011

**Revision Number:**

00

**Reason:**

Originally Published PCN