



Product Change Notification

107282 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107282 - 00

**Change Title: D946GZIS, PCN 107282-00,
Product Marking, Add RoHS label
for PRC, EI-CD refresh for
Windows Vista and Vreg controller
conversion**

Date of Publication: February 11, 2007

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 08, 2007
---	--------------

Description of Change to the Customer:

Add the RoHS markings to the D946GZIS Intel Desktop Board as a requirement for the People's Republic of China for retail products manufactured on or after 1 March 2007. The markings will appear as a label on the component side of the printed circuit board and on the motherboard packaging as well.

Updated Express Installer CD for Microsoft Windows Vista will be included.

An improved version of Vreg controller will be used to ensure product reliability.

Customer Impact of Change and Recommended Action:

This change has been thoroughly evaluated to ensure that there are no quality, reliability or functional implications to our customers. CDPG is not recommending additional qualification of these changes on platforms received from Intel. These board changes are not expected to cause a change to the Microsoft* Windows* operating system's software driver stack. No expected OS image change.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change AA	Pre Change PBA	Post Change TA	Post Change AA	Post Change PBA
LAD946GZISL 880261	880261	D61679- 301	D45436- 402	D45437- 402	D61679- 302	D45436- 403	D45437- 403
BLKD946GZISSL	882970	D59260-	D83227-	D83229-	D59260-	D83227-	D83229-

882970		102	402	402	103	403	403
BOXD946GZISSL 882974	882974	D62389- 103	D66165- 401	D66166- 401	D62389- 104	D66165- 402	D66166- 402

Reference Documents / Attachments:

Document: _____ **Location #:** _____

PCN Revision History:

Date of Revision: February 11, 2007	Revision Number: 00	Reason: Originally Published PCN
---	-------------------------------	--