



Product Change Notification

Change Notification #: 114359 - 00
Change Title: Intel® Xeon Phi™ Coprocessor 3120A PCIe Card,
Intel® Xeon Phi™ Coprocessor 3120A PCIe Card,
Intel® Xeon Phi™ Coprocessor 3120P PCIe Card,
Intel® Xeon Phi™ Coprocessor 5120D Dense Form,
SKUs SC3120AS; SC3120PS; SC5120DS;
SC3120PEBS; SC3120AEBS; SC3120AIBS
PCN 114359-00, Product Design,
BIOS Update
Date of Publication: January 28, 2016

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 2015
---	----------

Description of Change to the Customer:

The Intel® Xeon Phi™ Coprocessor 3120A, Intel® Xeon Phi™ Coprocessor 3120P, and Intel® Xeon Phi™ Coprocessor 5120D SKUs listed in the products affected table below will have the following change.

- The wrong SSID was included in the build of certain board SKUs. The BIOS will be updated to correct the SSID. As a result of this change the PBA and TA numbers will roll to the next dash level.

Customer Impact of Change and Recommended Action:

This change was originally implemented in 2015 and due to unknown reasons the Product Change Notification was not sent out.

Intel recommends that the customers perform a standard level of evaluation.

Intel does not expect any impact to customers from these changes, but encourage customers to understand the changes and determine impact to their applications.

Please contact your local Intel Field Sales Rep if you have any further questions about this change.

Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
SC3120AS	927500	G65759-352	G65493-352	G65759-353	G65493-353
SC3120PS	927501	G82474-352	G88044-352	G82474-353	G88044-353
SC5120DS	927503	G61933-252	G43066-252	G61933-253	G43066-253
SC3120PEBS	931160	H13740-352	G88044-352	H13740-353	G88044-353
SC3120AEBS	931161	H13668-352	G65493-352	H13668-353	G65493-353
SC3120AIBS	931162	H13708-352	G65493-352	H13708-353	G65493-353

PCN Revision History:**Date of Revision:**

January 28, 2016

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

114359 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.