



# Product Change Notification

**Change Notification #:** 119339-00

**Change Title:** Select Intel® Stratix® 10 Devices,  
PCN 119339-00, Product Design,  
Minor Substrate Change

**Date of Publication:** November 14, 2022

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

Last date to acknowledge receipt of this notification <sup>1</sup>	November 30, 2022
Earliest change implementation	January 30, 2023

Note 1: J-STD-046, section 3.2.3.1b, stipulates that lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change.

## Description of Change to the Customer:

This is the same change described in PCN2227 Rev 1.1.0 issued on November 8, 2022.

Intel is announcing a minor change to the substrate routing related to the unconnected Advanced Interface Bus (AIB) for selected Intel Stratix® 10 devices. The rest of the Bill of Material (BOM) remains the same.

## Reason for Change:

Continuous improvement on production test coverage of unconnected Advanced Interface Bus (AIB).

## Qualification Testing:

Package design review data indicated no significant impact to performance and reliability. Electrical verification tests were successfully completed to evaluate effectiveness of the change. ESD Charge Device Model test was also performed to ensure no impact to the ESD CDM threshold. (See Table 4)

**Table 4: ESD CDM Results**

Test	Conditions	# of Lots/ # of units	Result
ESD Charged Device Model (CDM)	+/- 250V	3 Lots/9 units	0 failures/Pass
	+/-350V	3 Lots/3 units	

## Customer Impact of Change and Recommended Action:

There is no impact to form, fit, and function. The products will meet existing electrical and mechanical specifications.

Customers are requested to:

1. Acknowledge receipt of this notification.
2. Review and inform us, at the earliest convenience, of any questions or concerns regarding this change.

Upon implementation, Intel will ship either pre-change or post-change materials.

For more information, please contact Sales in your region, or submit a Service Request at the [My Intel](#) support page.

## Products Affected/Intel Ordering Codes:

Product Family	Pin Count
Selected Intel® Stratix 10 SX	F1760
Selected Intel® Stratix 10 GX	F1760

The list of affected part numbers (OPNs) can be downloaded in Excel form:

<https://cdrdv2.intel.com/v1/dl/getContent/751575>

## PCN Revision History:

**Date of Revision:**

November 14, 2022

**Revision Number:**

00

**Reason:**

Originally Published PCN



# Product Change Notification

## 119339-00

### Notices & Disclaimers

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade, except as provided in a separate written agreement.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes the subject matter disclosed herein.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Statements in this document that refer to future plans or expectations are forward-looking statements. These statements are based on current expectations and involve many risks and uncertainties that could cause actual results to differ materially from those expressed or implied in such statements. For more information on the factors that could cause actual results to differ materially, see our most recent earnings release and SEC filings at [www.intc.com](http://www.intc.com).

Customer is responsible for safety of the overall system, including compliance with applicable safety-related requirements or standards.

Intel technologies may require enabled hardware, software or service activation.

No product or component can be absolutely secure.

Your costs and results may vary.

©Intel Corporation. Intel, the Intel logo, and other Intel marks are trademarks of Intel Corporation or its subsidiaries. Other names and brands may be claimed as the property of others.

No response from customers will be deemed an acceptance of the change, and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below.

**Americas Contact:** [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

**Asia Pacific/PRC Contact:** [apacgccb@intel.com](mailto:apacgccb@intel.com)

**Europe Email:** [eccb@intel.com](mailto:eccb@intel.com)

**Japan Email:** [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)