



Product Change Notification

Change Notification #: 114376 - 00
Change Title: Intel® Ethernet Server Adapter I210-T1, OEM Generic and Retail, Product Codes / MMs: I210T1, MM# 921433, I210T1BLK, MM# 921434, I210T1G1P20, MM # 921435; Intel® Gigabit CT Desktop Adapter, Bulk and Retail and Intel® Gigabit CT2 Desktop Adapter, OEM Generic, Product Codes / MMs: EXPI9301CT, MM# 893646 , EXPI9301CTBLK, MM# 893647; E1G31CTG1P20, MM# 908804
PCN 114376-00, Label
Label Update
Date of Publication: February 9, 2016

Key Characteristics of the Change:

Label

Forecasted Key Milestones:

| | |
|---|--------------|
| Date Customer Must be Ready to Receive Post-Conversion Material: | Feb 29, 2016 |
|---|--------------|

Description of Change to the Customer:

The Intel® Ethernet Server Adapter I210-T1, OEM Generic and Retail, Product Codes / MMs: I210T1, MM# 921433, I210T1BLK, MM# 921434, I210T1G1P20, MM # 921435; Intel® Gigabit CT Desktop Adapter, Bulk and Retail and Intel® Gigabit CT2 Desktop Adapter, OEM Generic, Product Codes / MMs: EXPI9301CT, MM# 893646 , EXPI9301CTBLK, MM# 893647; E1G31CTG1P20, MM# 908804, will undergo the following update:

Australia Regulatory Mark Change:

- The Australian Communications and Media Authority's (ACMA) labeling arrangements to reflect regulatory compliance changed on 1 March 2013, to be phased in over a three-year transition period. Products shipping March 1, 2016 need to be labeled with the "RCM" mark.
- Per ACMA requirements, Intel will be changing the C-Tick regulatory mark on all products to the "RCM" mark.
- Mark will be updated in two ways, depending on how the current C-Tick mark is already on products:
 - If C-Tick mark is currently on PCB silkscreen, Intel will apply a label with RCM mark to cover current mark.
 - If C-Tick mark is currently printed on a label, Intel will replace the mark so labels will be printed with new mark.

- See for picture of "C-Tick" versus "RCM" mark.



Customer Impact of Change and Recommended Action:

Intel anticipates no functional impact to customer but encourages customer to understand the changes. Customers can expect to receive mixed inventory until current inventory levels have been depleted. Please contact your local Intel Field Sales Rep if you have any further questions about these changes.

Products Affected / Intel Ordering Codes:

| Product Code | MM# |
|---------------------|------------|
| EXPI9301CT | 893646 |
| EXPI9301CTBLK | 893647 |
| E1G31CTG1P20 | 908804 |
| I210T1 | 921433 |
| I210T1BLK | 921434 |
| I210T1G1P20 | 921435 |

PCN Revision History:

Date of Revision:

February 9, 2016

Revision Number:

00

Reason:

Originally Published PCN



Product Change Notification

114376 - 00

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific/PRC Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2016. Other names and brands may be claimed as the property of others.

BunnyPeople, Celeron, Celeron Inside, Centrino, Centrino Inside, Cilk, Core Inside, i960, Intel, the Intel logo, Intel AppUp, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Insider, the Intel Inside logo, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel Sponsors of Tomorrow, the Intel Sponsors of Tomorrow logo, Intel StrataFlash, Intel vPro, Intel XScale, InTru, the InTru logo, the InTru Inside logo, InTru soundmark, Itanium, Itanium Inside, MCS, MMX, Moblin, Pentium, Pentium Inside, Puma, skool, the skool logo, Sound Mark, The Creators Project, The Journey Inside, Thunderbolt, vPro Inside, VTune, Xeon, and Xeon Inside are trademarks of Intel Corporation in the U.S. and/or other countries.

Learn how to use Intel Trademarks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.