



# Product Change Notification

## 109427 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

**Americas Contact:** <mailto:asmo.pcn@intel.com>

**Asia Pacific Contact:** <mailto:apacgccb@intel.com>

**Europe Email:** <mailto:eccb@intel.com>

**Japan Email:** <mailto:jccb.ijkk@intel.com>

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109427 - 01  
**Change Title:** D945GCLF2, PCN 109427-01, Product Design, Upgrade BIOS, Reason for Revision: Correction to AA numbers  
**Date of Publication:** June 16, 2009

## Key Characteristics of the Change:

Product Design

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Jul 13, 2009
---	--------------

## Description of Change to the Customer:

### Reason for Revision: Correction to AA numbers

Intel has implemented the following change to this sku:  
- Upgrade BIOS to LF94510J.86A.0182.2009.0528.2014. To access release notes or a copy of the BIOS for evaluation, go to [http://downloadcenter.intel.com/filter\\_results.aspx?strTypes=all&ProductID=2926&OSFullName=OS+Independent&lang=eng&strOSs=38&submit=Go%21](http://downloadcenter.intel.com/filter_results.aspx?strTypes=all&ProductID=2926&OSFullName=OS+Independent&lang=eng&strOSs=38&submit=Go%21).

Revision to correct AA numbers.

## Customer Impact of Change and Recommended Action:

It is recommended that customers evaluate this new BIOS to ensure a smooth transition. This change has been thoroughly evaluated to ensure that there are no quality, reliability, or functional implications to our customers. Intel is not recommending additional qualification of these changes on desktop boards received from Intel. This change is not expected to cause a change to the Microsoft Windows\* operating system's software driver stack.

## Products Affected / Intel Ordering Codes:

Product Code	MM#	Pre Change AA	Post Change AA
BOXD945GCLF2	896272	E46416-106	E46416-107
BLKD945GCLF2	896273	E46416-106	E46416-107
LAD945GCLF2	896275	E46417-109	E46417-110
BOXD945GCLF2D	901738	E59323-103	E59323-104
BLKD945GCLF2D	901768	E59323-103	E59323-104
LAD945GCLF2D	901740	E59321-103	E59321-104

## Reference Documents / Attachments:

Document:

Location #:

## PCN Revision History:

Date of Revision:

Revision Number:

Reason:

June 15, 2009

00

Originally Published PCN

June 16, 2009

01

Correction to AA numbers