



Product Change Notification

109018 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 109018 - 01
Change Title: SR1530CLR; SR1530HCLR; SR1530HCLSR, PCN 109018-01, Product Design, Update BIOS to R0096; Update to SMS 3.1 DVD; Update the attention doc, Reason for Revision: Update BIOS version and Update to SMS3.1 DVD; add attention doc change
Date of Publication: February 09, 2009

Key Characteristics of the Change:

Product Design

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Apr 03, 2009
---	--------------

Description of Change to the Customer:

Reason for Revision: Update BIOS version and Update to SMS3.1 DVD; add attention doc change

The Intel(R) Server Board software in Intel(R) Server System SR1530CLR; SR1530HCLR; SR1530HCLSR is being updated to BIOS production R0096 (see BIOS release notes for details).
Updating the Server Management Software 3.0 DVD to Server Management Software 3.1 DVD.
The attention document is also being updated.

Customer Impact of Change and Recommended Action:

Customers to place future orders using new order code.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
SR1530CLR	892052	E20937-007	D41874-702	901621	E20937-008	D41874-703
SR1530HCLR	892054	E20943-006	D41874-702	901622	E20943-007	D41874-703
SR1530HCLSR	892060	E20944-006	D24481-702	901624	E20944-007	D24481-703

Pre Conversion	Pre Conversion	Post Conversion
----------------	----------------	-----------------

Product Code	MM#	MM#
SR1530HCLSRNA	892047	901696
SR1530CLRNA	892053	901617
SR1530HCLRNA	892057	901695

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

Revision Number:

Reason:

January 4, 2009

00

Originally Published PCN

February 9, 2009

01

Update BIOS version and Update to SMS3.1 DVD; add attention doc change