



Product Change Notification

107060 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107060 - 01
Change Title: Selected Intel Chipsets, Processors, Microcontrollers, and Networking Components Marked with Former Intel® Logo, PCN 107060-01, Product Marking, Reason for Revision: Correct Products Affected Listing
Date of Publication: October 9, 2007

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Mar 08, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Add Additional Product(s)

Intel will be converting all of their components marked with the former Intel® logo, to the new mark shown below. Intel has done a best effort to ensure we've correctly identified all affected components, however it is possible that we have missed some of our newer products that were launched during this transition. Please note customers should be prepared to accept both product marks.

In January of 2006 Intel announced the introduction of the new brand logo to be used by all products sold by Intel. This notification is to announce the implementation plans for the new Intel logo change for "Components" products and how it impacts customers. Over the next few months Intel will be replacing the former Intel dropped "e" marking with a new marking. Customers will begin seeing the new product mark as shown in the picture below.

Customers may begin receiving a mix of old Intel logo and the new Intel product marks within a shipment until depletion of all pre-conversion material.

Customer Impact of Change and Recommended Action:

Intel anticipates no impact to form, fit, function, or reliability of any of the products affected by this change. Customers may want to notify their receiving departments of the new product mark change.

Products Affected / Intel Ordering Codes:

Product Code	S-Spec	MM#
A80486DX2SA66	S X911	800948
A80486DX4WB100	S K096	801069
KU80486SXSA25	S X934	801281
A80486SXSA33	S X931	801301
KU80486SXSA33	S X935	801318
N80959SA20		802779
N80959SB16		802787
A8095925	S V812	802805
A80960CA16		802846
A80960CA25		802884
A80960CA33		802946
A80960CF25		803021
A80960CF33		803084
A80960CF40		803133
A80960KA16		803435
TA80960KA20		803470
A80960KA25		803490
TA80960KB16		803510
A80960KB20		803516
TA80960KB20		803529
A80960KB25		803535
TA80960KB25		803546
SB82371SB	S U093	805436
KU82596CA25	S N213	806718
KU82596CA25	S Z716	806726
KU82596CA33	S N222	806758
KU82596DX25	S N189	806798
KU82596DX25	S Z714	806807
KU82596DX33	S Z715	806835
KU82596SX20	S Z713	806867
A80386DX16		807050
A80386DX20		807066
A80386DX25		807094
A80386DX25	S X158	807106
A80386DX33		807129
A80386DX33	S X181	807135
FW82439HX	S U115	807787
A80486DX4WB100	S K101	808894
FW82439TX	S L28T	813149
A80960HA40	S L2GZ	813628
A80960HT75	S L2GP	814114
A80960HD80	S L2GK	815177
A80960HD66	S L2GJ	815230
A80960MC25		816319
FW82443BX	S L2VH	818428
A80960JA3V33		819529
A80960JD3V66		819538
A80960JF3V25		819540

Product Code	S-Spec	MM#
A80960JF3V33		819542
FW80960VH100		820682
FW82371EB	S L37M	820763
GC80503CSM66166	S L388	821225
GC80503CSM66266	S L389	821226
FW82371EB	S L3AU	821640
FW82439TX	S L3BT	821840
GC80503CS166EXT	S L3B8	822631
FW82443MX100	S L3N4	824918
FW82810E	S L3MD	825101
FW82810	S L3P7	825102
FW82840	S L3TA	826059
FW82806AA	S L3VZ	827923
FW80960VH100	S L4PH	831141
RB80526RX733128	S L52Y	833440
RB80526RY850128	S L54Q	833470
FWLXT9784BE.A3		833561
FW82801E	S L5AW	834851
FWLXT9784BC.A3		834928
RB80526RX566128	S L5L5	835762
FW82815	S L5NQ	836138
FW82830MP	S L5P7	836388
FW82801BA	S L5WK	838027
FW82801CAM	S L5YP	838981
FW82830M	S L62D	841189
FW82830MG	S L62E	841198
FW82801CA	S L632	843132
GCIXE2424EC.B1		845040
FW82801DBM	S L6DN	848109
FW82801DB	S L6DM	848140
HBLXT9781HC.C5	S E001	851949
GCIXE5416EC.C0		856474
GCIXE5216EC.C0		856521
NH82830MP	S L7A6	857389
NH82801CAM	S L7A7	857393
NH82801IR	S LA9N	890311
FW82801DBL	S L7CN	858191
JA80386EXTB25		863487
JA80486GXSF338		863488
JA80486SXSf338		863490
JA80386EXTC25		863491
JA80386EXTC33		863492
UG80486DX4WB100	S L2M9	863493
UG80960HD5016	S L2GM	863959
UG80960HD8016	S L2LZ	863961
EE80960SA20512	S W227	863970
EE80960SA20512		863973
EN80960SA16512		863974
EE80960SA16512	S W226	863979
EE80960SA16512		863981

Product Code	S-Spec	MM#
EE80960SA16512	S W226	863979
EE80960SA16512		863981
UG80960HA4016	S L2GW	863985
EE80960SB16512		863986
EE80960SB10512		863988
EE80960SB16512	S W232	864010
NH82801BA	S L7UU	864013
PR80960VH100	S L4PH	864014
NH82815	S L7UT	864020
UG80960HD6616	S L2GN	864025
PR80960VH100		864026
UG80960HT7516	S L2GT	864027
UG80960HA3316	S L2GV	864032
UG80960HA2516	S L2GU	864034
EE80960SA10512	S W225	864037
NT80386DX25		864042
NT80386DX33		864044
YW80486DX2SC508	S X920	864076
NT80386DX33	S X692	864385
EG80C196EA		864391
NH82801DBM	S L7VK	864814
NH82810 S L7XK	S L7XK	865225
NH82810E S L7XL	S L7XL	865249
NH82443BXE	S L85Y	867048
NH82371EBE	S L87F	867346
GDLXT12101BC.A2	S L8AB	868302
GDLXT12101BC.A2	S L8AA	868327
NH82801CA	S L8AN	868447
NH82801DB	S L8DE	869490
NH82443MX100	S L8BQ	869847
NH82801E	S L8LG	871695
WDLXT9880AGE.A5		873056
QCIXE2424EC.B2	S L8ST	874001
NH82830M	S L8V9	875365
N82802AC8		825123
N82802AC8	S B48	825129
FW82801EB	S L73Z	853967
FW82801ER	S L742	853968
FW82801FB	S L7AG	857492
FW82801FR	S L79N	857493
FW82801FRW	S L7LT	861932
FW82801FBM	S L7W6	864873
FW82801FR	S L7W7	864874
FW82801FRW	S L7W8	864876
FW82801FB	S L7Y5	865377
FW82801FW	S L7Y6	865378
NH82801EB	S L7YC	865579
NH82801FBM	S L89K	868158
NH82801FR	S L89J	868159
NH82801FB	S L89L	868390

Product Code	S-Spec	MM#
FW82801FB	S L8BZ	869144
FW82801FR	S L8C2	869462
FW82801FAC	S L8DF	869527
NH82801GR	S L8FY	870293
NH82801GB	S L8FX	870379
FW82801GR	S L8KL	871525
FW82801GB	S L8TF	874363
NH82801GDH	S L8UK	874846
NH82801ER	S L8WB	875684
NH82801GBM	S L8YB	876595
NH82801GHM	S L8YR	876784
NH82801FB	S L9G8	882319
NH82801HR	S L9MK	883292
NH82801HH	S L9ML	883304
NH82801HO	S L9MM	883305
NH82801HB	S L9MN	883306

Reference Documents / Attachments:

Document:

Location #:

Example of Current Mark



Example of New Mark



Date of Revision:

December 8, 2006

October 9, 2007

Revision Number:

00

01

Reason:

Originally Published PCN

Correct Products Affected Listing