



Product Change Notification

110310 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apagccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 110310 - 00
Change Title: Intel® Server Board S3420GPLC, S3420GPLX, S3420GPRX, S3420GPV and Intel® Server System SR1630GP, SR1630GPRX, SR1630HGP, SR1630HGPRX, PCN 110310-00, Documentation, Update Intel(R) Server Deployment Toolkit CD and Update BIOS, BMC and FRUSDR
Date of Publication: November 09, 2010

Key Characteristics of the Change:

Documentation

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Dec 27, 2010
---	--------------

Description of Change to the Customer:

Intel will implement the following changes:

- 1) The Intel(R)Server Deployment Toolkit CD is being updated from E67735-006 to E67735-007 to include the Intel(R) Deployment Assistant 3.6, new drivers and documentation on the Intel(R) Server Board S3420GPLX, S3420GPLC, S3420GPRX, S3420GPV and the Intel(R) Server System SR1630GP, SR1630HGP, SR1630GPRX, SR1630HGPRX.
- 2) The BIOS version is being updated from 42 to 46, the BMC version is being updated from 19 to 23, and FRUSDR version is being updated from 17 to 18 on the Intel(R) Server Board S3420GPLX, S3420GPLC, and the Intel(R) Server System SR1630GP, SR1630HGP.
- 3) The BIOS version is being updated from 42 to 46 on the Intel(R) Server Board S3420GPV.
- 4) The BIOS version is being updated from 42 to 46, the BMC version is being updated from 19 to 23, and FRUSDR version is being updated from 05 to 08 on the Intel(R) Server Board S3420GPRX and the Intel(R) Server System SR1630GPRX, SR1630HGPRX.

The Intel(R) Server Deployment Toolkit CD and the system software update package, including Release notes for each, will be available for download from Intel's support website http://www.intel.com/p/en_US/support/highlights/server/s3420gp prior to this change. Please see software release notes for a list of changes when available.

Customer Impact of Change and Recommended Action:

Intel does not foresee any adverse customer impact from these changes. Intel recommends that the customer perform a standard level of evaluation as updated product and software become available.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	MM#	Pre Change TA	Pre Change PBA	Post Change TA	Post Change PBA
S3420GPV	902726	E84395-108	E80883-106	E84395-109	E80883-107
S3420GPRX	905452	E85654-305	E77063-303	E85654-306	E77063-304
S3420GPLC	907524	E74801-407	E51976-405	E74801-408	E51976-406
S3420GPLX	907525	E74800-407	E51974-405	E74800-408	E51974-406
SR1630GPRX	905453	E84849-005	E77063-303	E84849-006	E77063-304
SR1630HGPRX	905454	E84850-005	E77063-303	E84850-006	E77063-304
SR1630GP	907506	E65196-008	E51976-405	E65196-009	E51976-406
SR1630HGP	907517	E65540-008	E51976-405	E65540-009	E51976-406
SR1630GPNA	905769	E65196-008	E51976-405	E65196-009	E51976-406
SR1630HGPNNA	905819	E65540-008	E51976-405	E65540-009	E51976-406
SR1630GPRXNA	904388	E84849-005	E77063-303	E84849-006	E77063-304
SR1630HGPRXNA	904504	E84850-005	E77063-303	E84850-006	E77063-304
BB3420GPV	902728	E89003-106	E77063-303	E89003-107	E77063-304
BB3420GPLC	907526	E77963-405	E51976-405	E77963-406	E51976-406
BB3420GPLXSASM	909787	G14597-001	E51974-405	G14597-002	E51974-406

PCN Revision History:

Date of Revision:

November 9, 2010

Revision Number:

00

Reason:

Originally Published PCN