



# Product Change Notification

## 109588 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2009. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109588 - 00  
**Change Title:** Intel(R) Server Board S3210SHLC,  
S3200SHV, S3210SHLX, PCN 109588-00,  
Product Material, Resource CD is updated  
**Date of Publication:** September 28, 2009

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Oct 23, 2009
---	--------------

## Description of Change to the Customer:

Resource CD is updated to include Intel(R) Deployment Assistant 2.5.1, and updated drivers, utilities, product documentations. The Intel Product Number for the resource CD is changing from E11124-004 to E11124-006.

## Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers, but encourages customers to evaluate the Resource CD with their applications.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Pre Change PBA	Post Change MM#	Post Change TA	Post Change PBA
S3210SHLX	901999	E12673-304	D88308-302	901999	E12673-305	D88308-302
S3210SHLC	902001	E12677-304	D86139-302	902001	E12677-305	D86139-302
S3200SHV	902002	E12678-304	D86141-302	902002	E12678-305	D86141-302

## Reference Documents / Attachments:

**Document:** \_\_\_\_\_ **Location #:** \_\_\_\_\_

## PCN Revision History:

<b>Date of Revision:</b> September 28, 2009	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
--	-------------------------------	--