



# Product Change Notification

## 109905 - 00

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: [asmo.pcn@intel.com](mailto:asmo.pcn@intel.com)

Asia Pacific Contact: [apacgccb@intel.com](mailto:apacgccb@intel.com)

Europe Email: [eccb@intel.com](mailto:eccb@intel.com)

Japan Email: [jccb.ijkk@intel.com](mailto:jccb.ijkk@intel.com)

Copyright © Intel Corporation 2010. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



# Product Change Notification

**Change Notification #:** 109905 - 00  
**Change Title:** DQ57TM, PCN 109905-00, Product Material, BIOS update, Set TPM nvLocked Permanent Flag  
**Date of Publication:** March 24, 2010

## Key Characteristics of the Change:

Product Material

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	Mar 11, 2010
---	--------------

## Description of Change to the Customer:

BIOS update from TMIBX10H.86A.0025 to TMIBX10H.86A.0029. To access the release notes or a copy of the BIOS for evaluation, go to <http://downloadcenter.intel.com>

Set the Permanent Flag "nvLocked" of the Trusted Platform Module (TPM) Non-Volatile Random Access Memory (NVRAM), resolving a possible issue with the Intel(R) Brand Verification Tool (Intel(R) BVT) and Intel Trusted Execution Technology (Intel(R) TXT).

## Customer Impact of Change and Recommended Action:

Intel anticipates no impact to customers, see PCN detail for further information.

## Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change AA	Post Change AA
BOXDQ57TM 903543	903543	E70931-400	E70931-401
BLKDQ57TM 903547	903547	E70931-400	E70931-401

## Reference Documents / Attachments:

**Document:** **Location #:**

## PCN Revision History:

<b>Date of Revision:</b> March 24, 2010	<b>Revision Number:</b> 00	<b>Reason:</b> Originally Published PCN
--	-------------------------------	--